Appendix F Design Standards Inventory



Kayenta Airport Airport Master Plan

Airside Inventory Checklist

Airport Kayenta ARC B-II
City Kayenta, Arizona Approach Type Visual
Contact Phillip Zahne Date Inventoried 9/29/04

Phone No. (928) 697-8451	Inspected By DC			
Runway 5/23 Inventory	Published	Required	Actual	
Distance To:	TOWNIN COURT			
Hold lines from centerline	-	200	203	
Parallel taxiway from centerline	N/A	240	N/A	
Aircraft parking from centerline	· <u>-</u>	250	350	
Runway width	75	75	75	
Runway length	7,140	To be determined	7,140	
RSA width		150	150(1)	
ROFA width	-	500	500	
Primary/transitional surface penetrations	-	Clear	4' brush	
Longitudinal grade - site distance problems	<u>-</u>	Clear	Clear	
OFZ	-	250X200	250x200	
Pavement marking type	Basic	Visual	Visual	
Pavement marking condition	Good	-	Fair	
Pavement strength	12,500 (SWG)	-	12,500	
Pavement condition	Fair	-	Poor (2)	
		-		
Runway 5 End Inventory				
RSA beyond runway end	9300-010	300	300	
ROFA beyond runway end		300	300	
Approach obstructions	None	None	None	
Runway end elevation	5700' MSL	-	To be surveyed	
Runway Lighting Inventory				
Distance from pavement edge	_	10	10	
Maximum distance between lights	, , , , , , , , , , , , , , , , , , , ,	200	200	
Type	MIRL	MIRL	MIRL	
			Fair-stake mounted	
Condition	-	_	Direct Burial	
			White	
Color	-	White	several missing	
Other: Control (manual, photocell, pilot)	Dusk-Dawn	Dusk-Dawn	Dusk-Dawn	
Runway 5 Threshold				
Distance from pavement edge	_	10	10	
Maximum distance between lights	-	100		
Color	-	Green/Red	Green/Red	
Number of lights	_	6	4 (2 missing)	
Runway 23 End Inventory				
RSA beyond runway end		300	300	
ROFA beyond runway end		300	300	
Approach obstructions	None	None	None	
Runway end elevation	5625' MSL	-	To be surveyed	
Runway 23 Threshold				
Distance from pavement edge	_	10	10	
Maximum distance between lights	, , , , , , , , , , , , , , , , , , ,			
Color		Green/Red	Green/Red	
Number of lights		6	5 (1 missing)	
Trainipor or ngma			J 5 (1.11.00m/g)	

COMMENTS (1) Erosion and vegetation growth along edges of safety area.

Others: Severe drainage problems, ponding near apron, taxiway, & runway.

⁽²⁾ Deep rutting, severe cracking, collapsing pavement.

Airside Inventory Checklist

Airport	Kayenta	ARC	B-II
City	Kayenta, Arizona	Approach Type	Visual
Contact	Phillip Zahne	Date Inventoried	9/29/04
Phone No.	(928) 697-8451	Inspected By	DC

Taxiway Inventory	Published	Required	Actual
Stub Connector		-	
Taixway width		35	35
TSA width		79	79
TOFA width		131	131
Dist. from centerline to fixed or movable ob		65.5	65.5
Pavement marking type		Centerline	
Pavement marking condition		_	Fair
Pavement strength	12,500		12,500
Pavement condition		NA	Poor (2)
Turnaround RWY 23			90x80
Turnaround RWY 5			90x85
Taxiway Lighting Inventory			
Distance from pavement edge	-	10	10
Maximum distance between lights	- 11	100	
Туре	- 1		MITL
			Fair stake mounted
Condition	-		Direct Burial
Color	-	Blue	Blue
Miscellaneous			
	White-Green		
Type of beacon	(land airport)	White-Green	White-Green
Size of beacon	- 1	-	2-light
Visual Aids (i.e. PAPI, VASI, REIL, etc.)	PVASI-RWY 23 (OTS)	<u></u>	PVASI-RWY 23
, , , , , , , , , , , , , , , , , , , ,	` '		(out of service)
Windcone (condition & compliance)	Yes-lighted		Good-lighted
Segmented circle (condition & compliance)	yes	- · · · · · · · · · · · · · · · · · · ·	Good
			5 strand-barbwire
			with mesh Poor-
Fencing		NA	missing sections
Signs (type, condition, placement)		NA	Poor(1)

Landside Inventory Checklist

Airport	Kayenta	ARC	B-II
City	Kayenta, Arizona	Approach Type	Visual
Contact	Phillip Zahne	Date Inventoried	9/29/04
Phone No.	(928) 697-8451	Inspected By	DC

Facilities	
Tie-downs	
T-hangars	
Box hangars	
Apron	
Size	
Pavement strength	
Pavement condition	
Pavement marking	
Pavement marking condition	
Automobile Access Automobile parking Airport signage (way finding) Taxilane Widths Weather equipment	
Fuel storage	
Fuel type available	
FBO/Terminal building	,

Existing
10
none
none
4,100 S.Y.
12,500
Fair
Good
Good
Paved road
Gravel/Dirt
None
79
None
8,000 gallons Jet A
6,000 gallons 100LL
None
None

Notes
e separation and build into wind
mall needs more pavement space
olled automobile access onto apron, , and runway. No gates or fencing. Poor (soft/wet/muddy)
feet needed for group II aircraft
Eagle Air Med Tanks
ate self fueling Eagle Air Med only)

COMMENTS_		 	



FILM CREW KING AIR 200



EAGLE AIR MED C-90



EAGLE AIR MED'S FUEL FARM




TAXIWAY PAVEMENT SURFACE (NOTE RUTTING)




CESSNA 182 ON RAMP (NOTE TIEDOWN DIRECTION)



AIRPORT BEACON (NOTE APRON DRAINAGE




HOLD LINE AND SIGN



CRACK SIZES




RUNWAY PAVEMENT AND SAFETY AREA



RUNWAY PAVEMENT (NOTE RUTTING)



RUNWAY TAXIWAY CONNECTOR



RUNWAY PAVEMENT