

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS	
ADOT	00486	8	B	.01	Colorado River Br	Southwest		1956	4	2	5	180	837	0	62	52	0	0	501	42	73		71.6	Good	NHS	
ADOT	01700	8		.01	Colorado River Viaduct EB	Southwest	I-8-9(2)	1978	6	5	15	214	2749	0	39	39	25	0	911	32	54		95.2	Good	NHS	
ADOT	01701	8		.01	Colorado River Viaduct WB	Southwest	I-8-9(2)	1978	6	5	14	220	2668	0	39	39	25	0	411	32	54		95.2	Good	NHS	
ADOT	00487	8	B	0.11	Yuma Canal Bridge	Southwest	NFA-407(56)A	1956	3	2	3	70	146	40	63	72	0		600	46	78		81.0	Fair	NHS	
ADOT	01322	8		0.58	4th St TI OP EB	Southwest	I-8-1(49)	1969	2	6	2	104	205	3	38	38	30.14		110	50	84		92.1	Fair	NHS	
ADOT	01323	8		0.58	4th St TI OP WB	Southwest	I-8-1(49)	1969	2	6	2	102	204	3	47	47	30.12		110	50	84		92.0	Fair	NHS	
ADOT	02075	8		.58	4th Street UPRR UP	Southwest	IG-8-1(62)C	1976	5	5	4	52	167	14	0	101	15.33	0	100	0	0		-2.0	Fair		
ADOT	01380	8		2.23	US 95 TI UP	Southwest	I-8-1(49)	1970	2	6	2	132	260	28	108	108	16.33	1	911	53	88		96.0	Fair	NHS	
ADOT	01381	8		2.99	Ave 2E UP	Southwest	I-8-1(49)	1970	2	6	2	127	258	15	76	72	16.35		211	41	69		88.3	Fair	NHS	
ADOT	02681	8		3.99	Ave 3E TI OP EB	Southwest	IM-008-A-(014)B	2003	6	6	2	111	213	13	38	42	18.03		911	52	96		98.0	Good	NHS	
ADOT	02682	8		3.99	Ave 3E TI OP WB	Southwest	IM-008-A-(014)B	2003	6	6	2	111	213	13	38	42	18.1		911	52	96		98.0	Fair	NHS	
ADOT	01277	8		7.67	Araby Rd TI OP EB	Southwest	I-G-8-1(42)	1968	2	4	4	52	147	8	38	38	15.23		110	46	77	F	92.0	Fair	NHS	
ADOT	01278	8		7.67	Araby Rd TI OP WB	Southwest	I-G-8-1(42)	1968	2	4	4	52	147	8	38	38	15.29		110	46	77	F	92.0	Fair	NHS	
ADOT	01279	8		8.69	Fortuna SPRR OP EB	Southwest	I-G-8-1(42)	1968	4	2	3	105	281	60	38	33	23.28		111	38	65		77.0	Fair	NHS	
ADOT	01280	8		8.7	Fortuna SPRR OP WB	Southwest	I-G-8-1(42)	1968	4	2	3	105	281	60	38	33	22.96		111	37	65		77.0	Fair	NHS	
ADOT	01188	8		9.43	E Yuma TI OP EB	Southwest	I-G-8-1(42)	1968	4	2	4	101	313	46	38	33	18.17		111	36	58		88.3	Fair	NHS	
ADOT	01281	8		9.44	E Yuma TI OP WB	Southwest	I-G-8-1(42)	1968	4	2	4	101	313	46	38	33	17.69		111	42	70		88.3	Fair	NHS	
ADOT	02432	8		12.2	Fortuna Rd TI UP	Southwest	NH-8-1(95)	1997	6	2	2	131	268	0	80	80	16.63		911	50	99		99.0	Good		
ADOT	02117	8		14.25	Foothills Blvd TI UP	Southwest	IR-8-1(88)	1990	6	2	2	131	267	9	80	84	16.58		911	44	99		79.3	Fair	NHS	
ADOT	01190	8		14.87	Fortuna Wash Br EB	Southwest	I-8-1(38)	1966	6	2	4	53	215	20	38	38	0	2	911	43	94		96.3	Fair	NHS	
ADOT	01191	8		14.87	Fortuna Wash Br WB	Southwest	I-8-1(38)	1967	6	2	4	53	215	20	38	38	0	2	911	43	94		96.4	Fair	NHS	
ADOT	01192	8		14.98	Frontage Rd OP EB	Southwest	I-8-1(38)	1966	2	1	3	35	94	0	38	38	15.53	2	911	42	70		94.3	Fair	NHS	
ADOT	01193	8		14.98	Frontage Rd OP WB	Southwest	I-8-1(38)	1966	2	1	3	35	94	0	38	38	15.81	2	911	42	70		94.4	Fair	NHS	
ADOT	05228	8		16.41	RCB WB	Southwest	I-8-1(38)	1967	2	19	4	10	49	30	38	0	0	-00	40	67			97.5	Good	NHS	
ADOT	07082	8		16.41	Dry Wash RCB EB	Southwest	BR-8-A(2)	2002	2	19	4	10	43	0	38	0	0	-00	40	67			97.4	Good	NHS	
ADOT	05229	8		16.79	RCB WB	Southwest	I-8-1(38)	1967	2	19	3	10	45	45	38	0	0	0	-00	38	64			97.5	Good	NHS
ADOT	01566	8		16.85	Dublin Wash Br EB	Southwest	NRH-8(8)B	1927	2	1	2	20	40	45	38	40	0	7	911	25	42			86.4	Fair	NHS
ADOT	06743	8		16.85	Insp Sta Ramp RCB EB	Southwest	I-8-1(77)	1982	2	19	2	12	38	49	34	0	0	0	-00	76	99			97.4	Good	NHS
ADOT	05230	8		17.76	RCB EB	Southwest	I-8-1(21)	1967	2	19	3	10	32	0	38	0	0	0	-00	42	70			97.4	Good	NHS
ADOT	05231	8		17.77	RCB WB	Southwest	I-8-1(21)	1967	2	19	3	10	32	0	38	0	0	0	-00	99	99			97.5	Good	NHS
ADOT	00303	8		18.12	Wash Br EB	Southwest	FAP-82B	1927	2	1	2	13	28	3	38	63.7	0	6	610	25	43			85.4	Good	NHS
ADOT	06714	8		18.5	RCB EB	Southwest	FAP-82B	1929	2	19	2	10	30	45	38	0	0		82	99			94.8	Good	NHS	
ADOT	00971	8		18.8	Telpas OP WB Over EB	Southwest	I-8-1(21)	1967	4	2	3	159	267	0	38	42.1	19.52		911	39	66			89.7	Fair	NHS
ADOT	00972	8		20.4	Telpas OP WB Over EB	Southwest	I-8-1(21)	1967	4	2	3	103	249	51	38	42.1	16.46		911	40	66			91.8	Fair	NHS
ADOT	01324	8		21.04	Dome Vly Rd TI UP EB	Southwest	I-8-1(35)	1969	2	4	3	70	183	29	34	34	19.42	0	911	37	63			98.1	Fair	
ADOT	01325	8		21.06	Dome Vly Rd TI UP WB	Southwest	I-8-1(35)	1969	2	4	3	68	155	17	34	34	16.23	0	911	43	73			95.4	Fair	
ADOT	05232	8		21.63	RCB	Southwest	I-8-1(35)	1969	2	19	2	12	25	0	150	0	0	0	-00	45	75			65.0	Good	NHS
ADOT	01327	8		22.9	Red Top Wash Br WB	Southwest	I-8-1(35)	1967	6	2	2	76	157	20	38	38	0		911	43	56			96.5	Fair	NHS
ADOT	01326	8		22.91	Red Top Wash Br EB	Southwest	I-8-1(35)	1967	6	2	2	76	157	20	38	38	0		911	43	56			95.5	Fair	NHS
ADOT	01328	8		24.1	Ligurta Wash Br EB	Southwest	I-8-1(35)	1967	6	2	6	78	469	30	38	38	0		911	36	94			96.5	Fair	NHS
ADOT	01329	8		24.1	Ligurta Wash Br WB	Southwest	I-8-1(35)	1967	6	2	6	78	469	30	38	38	0		911	36	94			96.5	Fair	NHS
ADOT	05233	8		26.53	RCB	Southwest	I-8-1(32)	1969	2	19	3	10	32	0	76	0	0	0	-00	41	69			81.8	Good	NHS
ADOT	01330	8		26.7	Ave 25E OP EB	Southwest	I-8-1(32)	1965	2	1	3	40	107	11	38	38	18.45		911	34	57	F		90.8	Fair	NHS
ADOT	01331	8		26.7	Ave 25E OP WB	Southwest	I-8-1(32)	1965	2	1	3	40	107	11	38	38	19.33	1	911	35	58	F		92.3	Fair	NHS
ADOT	05234	8		29.74	RCB	Southwest	I-8-1(32)	1969	2	19	2	10	21	0	76	0	0	0	-00	40	67			65.0	Good	NHS
ADOT	01332	8		30.8	Wellton TI UP	Southwest	I-8-1(32)	1965	2	4	4	81	254	15	40	40	16.2		111	46	77	F		92.8	Fair	NHS
ADOT	01333	8		31.5	Wellton Canal Br EB	Southwest	I-8-1(32)	1967	2	6	3	51	109	0	38	38	0		911	36	58			96.5	Fair	NHS
ADOT	01334	8		31.5	Wellton Canal Br WB	Southwest	I-8-1(32)	1967	2	6	3	51	109	0	38	38	0		911	36	58			96.6	Fair	NHS
ADOT	05236	8		32.37	RCB	Southwest	I-8-1(29)	1969	2	19	3	10	32	0	76	0	0	0	-00	99	99			82.0	Good	NHS
ADOT	01335	8		32.89	Ave 31E UP	Southwest	I-8-1(29)	1965	2	6	4	85	262	16	26	26	16.28		111	35	59			97.8	Fair	NHS
ADOT	05237	8		33.91	RCB	Southwest	I-8-1(29)	1969	2	19	3	10	32	0	76	0	0	0	000	99	99			82.0	Good	NHS
ADOT	01336	8		34.91	Ave 33E UP	Southwest	I-8-1(29)	1964	5	2	9	78	613	5	28	28	20.33		311	36	96			96.9	Good	
ADOT	02738	8		36.4	Mohawk Canal Br OP EB	Southwest	-800-A(003)A	2003	5	6	1	151	252	50	38	42	0		911	38	99			96.5	Fair	NHS
ADOT	02739	8		36.4	Mohawk Canal Br OP WB	Southwest	-008-A(003)A	2003	5	6	1	151	253	55	38	42	0		911	48	99			95.8	Fair	NHS
ADOT	01194	8		37.98	Antelope Hill TI UP	Southwest	I-8-1(26)	1967	4	2	4	81	258	14	32	30	16.25		911	38	64	F		86.8	Fair	NHS
ADOT	05239	8		40.71	RCB	Southwest	I-8-1(26)	1966	2	19	2	10	21	0	76	0	0	0	-00	84	99			73.7	Good	NHS
ADOT	01195	8		42.08	Tacna TI UP	Southwest	I-8-1(26)	1967	4	2	4	79	254	10	32	33	16.47		911	39	65	F		95.8	Fair	NHS
ADOT	05241	8		42.62	RCB	Southwest	I-8-1(26)	1966	2	19	2	10	21	0	76	0	0	0	-00	43	72			74.1	Good	NHS
ADOT	05243	8		44.61	RCB	Southwest	I-8-1(25)	1965	2	19	4	10	43	30	76	0	0	0	000	42	69			74.1	Good	NHS
ADOT	05245	8		45.81	RCB	Southwest	I-8-1(25)	1965	2	19	4	10	43	0	76	0	0	0	-00	40	66			74.1	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS	
ADOT	05247	8		46.28	RCB EB	Southwest	I-8-1(25)	1965	2	19	6	10	65	0	38	0	0	0	-00	99	99		97.6	Good	NHS	
ADOT	05248	8		46.28	RCB WB	Southwest	I-8-1(25)	1965	2	19	6	10	65	0	38	0	0	0	-00	80	99		97.7	Good	NHS	
ADOT	05249	8		52.11	RCB	Southwest	I-G-8-1(18)	1966	2	19	3	10	45	45	76	0	0	0		79	99		74.1	Good	NHS	
ADOT	01135	8		54.85	Mohawk SPRR OP EB	Southwest	I-G-8-1(18)	1966	4	2	3	58	153	30	38	38	23.9	2	300	36	60		94.6	Good	NHS	
ADOT	01136	8		54.85	Mohawk SPRR OP WB	Southwest	I-G-8-1(18)	1966	4	2	3	58	153	30	38	38	24.01	1	300	36	60		94.6	Good	NHS	
ADOT	06334	8		54.85	RCB FR	Southwest	I-8-1 (17)	1964	2	19	2	10	21	0	30	0	0	0		80	99		89.4	Good		
ADOT	00784	8		54.92	Mohawk TI OP EB	Southwest	I-8-1(17)	1963	2	4	3	56	158	51	38	38	15.21	2	911	42	71	F	92.6	Fair	NHS	
ADOT	00785	8		54.92	Mohawk TI OP WB	Southwest	I-8-1(17)55	1963	2	4	3	56	158	49	38	38	16.83	2	911	42	71	F	92.6	Fair	NHS	
ADOT	05251	8		55.33	RCB & Ramps	Southwest	IN-55(6)	1955	2	19	2	10	21	0	116	0	0	0		99	99		82.1	Fair	NHS	
ADOT	05253	8		55.54	RCB	Southwest	IN-55(6)	1955	2	19	4	10	43	0	76	0	0	0		43	72		69.9	Good	NHS	
ADOT	05255	8		59.55	RCB EB	Southwest	IN-55(6)	1955	2	19	5	10	54	0	38	0	0	0		41	69		97.6	Fair	NHS	
ADOT	05256	8		59.55	RCB WB	Southwest	I-8-1(13)	1962	2	19	5	10	54	0	38	0	0	0		82	99		97.7	Good	NHS	
ADOT	05257	8		59.97	San Cristobal RCB EB	Southwest	IN-55(6)	1955	2	19	6	10	65	0	38	0	0	0		41	69	S	70.5	Poor	NHS	
ADOT	05258	8		59.97	San Cristobal RCB WB	Southwest	I-8-1(13)	1962	2	19	6	10	65	0	38	0	0	0		41	69		97.7	Fair	NHS	
ADOT	00681	8		67.43	Dateland TI OP EB	Southwest	I-8-1(10)	1962	2	1	3	40	108	24	38	38	14.24	2	911	45	76		95.0	Fair	NHS	
ADOT	00682	8		67.43	Dateland TI OP WB	Southwest	I-8-1(10)	1962	2	1	3	40	108	24	38	38	14.21	2	911	45	76		95.0	Fair	NHS	
ADOT	05259	8		72.18	RCB	Southwest	IN-2-1(11)	1956	2	19	5	10	54	0	76	0	0	0		85	99		69.9	Good	NHS	
ADOT	00683	8		73.48	Aztec TI OP EB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	14.46	1	911	39	65		96.0	Fair	NHS	
ADOT	00684	8		73.48	Aztec TI OP WB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	14.48	1	911	39	65		96.0	Fair	NHS	
ADOT	05261	8		75.12	Canyon Diablo RCB	Southwest	IN-002-1(2)	1956	2	19	6	10	75	30	38	0	0	0		85	99		69.9	Fair	NHS	
ADOT	00685	8		78.4	Spot Rd TI OP EB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	13.88	1	911	42	69	F	94.0	Fair	NHS	
ADOT	00686	8		78.4	Spot Rd TI OP WB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	13.87	1	911	42	69	F	94.0	Fair	NHS	
ADOT	05263	8		83.01	RCB WB	Southwest	I-8-2(23)	1962	2	19	5	12	111	55	38	0	0	0		600	40	67		97.5	Fair	NHS
ADOT	00317	8		83.14	Wash Bridge EB	Southwest	FA-69-1 REO	1930	2	1	5	23	116	52	38	40	0	3	911	31	51		83.5	Fair	NHS	
ADOT	00687	8		87.04	Sentinel TI OP EB	Southwest	I-8-2(23)	1962	2	1	3	36	97	0	38	38	14.91	2	810	41	69		95.0	Fair	NHS	
ADOT	00688	8		87.04	Sentinel TI OP WB	Southwest	I-8-2(23)	1962	2	1	3	36	97	0	38	38	15.37	2	810	41	69		95.0	Fair	NHS	
ADOT	05264	8		87.25	RCB & Ramps & NFR	Southwest	FI-69(3)	1949	2	19	2	10	21	0	90	0	0	0		99	99		81.7	Good	NHS	
ADOT	05265	8		90.86	RCB	Southwest	FI-69(4)	1953	2	19	3	10	37	30	76	0	0	0		43	72		70.0	Good	NHS	
ADOT	05267	8		94.29	RCB	Southwest	FI-69(4)	1953	2	19	3	10	32	0	76	0	0	0		43	72		70.0	Good	NHS	
ADOT	05269	8		97.42	RCB	Southwest	FI-69(5)	1953	2	19	3	10	32	0	76	0	0	0		42	70		70.0	Good	NHS	
ADOT	00509	8		102.27	Painted Rock TI OP EB	Southwest	I-002-2(6)	1958	2	1	3	33	90	0	38	38	15.21	1	911	42	69	F	93.0	Fair	NHS	
ADOT	00510	8		102.27	Painted Rock TI OP WB	Southwest	I-002-2(6)	1958	2	1	3	33	90	0	38	38	15.36	1	911	42	69	F	93.0	Fair	NHS	
ADOT	00566	8		106.54	Paloma Rd TI OP EB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38	14.23	2	911	41	68		95.0	Fair	NHS	
ADOT	00567	8		106.54	Paloma Rd TI OP WB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38	14.33	3	911	41	68		95.0	Fair	NHS	
ADOT	00489	8		107.02	Gillespie Canal Br EB	Southwest	I(52)-I-002-2(1)	1957	2	1	2	21	43	30	38	40	0	2	911	24	41	S	59.0	Poor	NHS	
ADOT	01009	8		107.02	Gillespie Cnl Br SFR	Southwest	FAP-56	1923	2	1	2	22	45	20	40	45	0	2	400	24	41		85.7	Fair		
ADOT	00568	8		107.07	Gillespie Cnl Br WB	Southwest	I-8-2(18)	1960	2	1	2	21	43	35	38	38	0	3	911	36	61		96.6	Fair	NHS	
ADOT	00490	8		109.55	Gillespie Canal Br EB	Southwest	I(52)-IN002-2(1)	1957	2	1	2	25	51	0	38	40	0	3	911	26	43		88.0	Fair	NHS	
ADOT	00569	8		109.55	Gillespie Cnl Br WB	Southwest	I-8-2(18)	1960	2	1	2	25	51	5	38	38	0	2	911	37	62		96.6	Fair	NHS	
ADOT	01010	8		109.55	Gillespie Cnl Br SFR	Southwest	FAP-56(3)	1923	2	1	2	27	53	3	20	45	0	2	400	24	41		85.7	Fair		
ADOT	01505	8		110.35	Wash Bridge SFR	Southwest	FA-56 2ndRec	1923	1	1	2	22	44	0	22	22	0	4	400	25	43		71.6	Fair		
ADOT	05271	8		110.35	RCB	Southwest	IN-002-2(1)	1957	2	19	4	10	43	15	76	0	0	2		32	53		76.7	Fair	NHS	
ADOT	00570	8		111.42	Citrus Vly TI OP EB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38.7	14.73	1	911	40	67		96.0	Fair	NHS	
ADOT	00571	8		111.42	Citrus Vly TI OP WB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38.7	14.68	1	911	40	67		96.0	Fair	NHS	
ADOT	05273	8		112.01	RCB & SFR	Southwest	IN-002-2(1)	1938	2	19	2	10	21	3	76	0	0	0		40	67		71.2	Fair	NHS	
ADOT	00439	8		113.27	Sauceda Wash Br SFR	Southwest	FA-56(2R)	1930	2	1	4	22	89	0	24	24	0	3	111	25	42		78.1	Fair		
ADOT	00442	8		113.27	Sauceda Wash Br EB	Southwest	FI-56-3	1955	2	1	4	25	90	0	38	40	0	2	110	25	41		85.6	Fair	NHS	
ADOT	01554	8		113.27	Sauceda Wash Br WB	Southwest	I-G-8-2(40)	1971	2	1	4	30	111	30	38	38	0	0	110	40	67		94.6	Fair	NHS	
ADOT	06201	8		113.9	RCB & SFR	Southwest	I-G-8-2(40)	1971	2	19	3	12	44	30	76	0	0	0		97	99		81.8	Good	NHS	
ADOT	06202	8		114.29	RCB & SFR & NFR	Southwest	I-G-8-2(40)	1971	2	19	3	12	39	12	76	0	0	0		97	99		81.8	Good	NHS	
ADOT	01555	8		115.14	SB 8 & SPRR OP EB	Southwest	I-G-8-2(40)	1971	4	2	7	102	659	60	38	38	23.8		111	39	65		95.6	Fair	NHS	
ADOT	01556	8		115.14	SB 8 & SPRR OP WB	Southwest	I-G-8-2(40)	1971	4	2	7	102	659	60	38	38	23.62		111	39	65		95.6	Fair	NHS	
ADOT	06203	8		115.58	RCB	Southwest	I-G-8-2(40)	1971	2	19	3	10	37	30	76	0	0	0		99	99		82.5	Good	NHS	
ADOT	01557	8		115.62	Hwy 85 OP WB	Southwest	I-G-8-2(40)	1971	2	6	3	86	171	30	38	38	15.11		110	44	74		95.9	Fair	NHS	
ADOT	01558	8		115.62	Hwy 85 OP EB	Southwest	I-G-8-2(40)	1971	2	6	3	86	171	30	38	38	15.26		110	44	74		95.8	Fair	NHS	
ADOT	01394	8		115.95	Gila Bend Cnl Br EB	Southwest	I-G-8-2(44)	1965	5	2	1	85	90	34	47	47.9	0		400	39	90		86.8	Fair	NHS	
ADOT	01395	8		115.95	Gila Bend Cnl Br WB	Southwest	I-G-8-2(44)	1965	5	2	1	85	90	34	38	38	0		400	42	95		84.6	Fair	NHS	
ADOT	01339	8		116.35	TC & GBRR OP EB	Southwest	I-G-8-2(44)	1965	6	2	3	39	120	7	38	38	23.82		400	53	99		96.8	Fair	NHS	
ADOT	01340	8		116.35	TC & GBRR OP WB	Southwest	I-G-8-2(44)	1965	6	2	3	39	120	7	38	38	23.65		400	48	99		96.6	Fair	NHS	
ADOT	01341	8		116.76	County Rd OP EB	Southwest	I-G-8-2(44)	1965	2	1	3	40	107	17	38	38	15.43		400	36	59		94.8	Fair	NHS	

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
ADOT	01342	8		116.76	County Rd OP WB	Southwest	I-IG-8-2(44)	1965	2	1	3	40	107	17	38	38	15.58		400	36	59		94.6	Fair	NHS
ADOT	06493	8		116.87	RCB	Southwest	I-IG-8-2(44)	1970	2	19	2	10	29	45	76	0	0	0		99	99		82.4	Good	NHS
ADOT	06494	8		117.29	RCB	Southwest	I-IG-8-2(44)	1970	2	19	5	10	54	0	76	0	0	0		40	66		82.4	Good	NHS
ADOT	01343	8		117.43	Sand Tanks Wash Br EB	Southwest	I-IG-8-2(44)	1965	2	1	7	30	201	45	38	38	0		110	40	68		84.8	Fair	NHS
ADOT	01344	8		117.43	Sand Tanks Wash Br WB	Southwest	I-IG-8-2(44)	1965	2	1	7	30	201	45	38	38	0		110	37	63		84.6	Fair	NHS
ADOT	06495	8		117.5	RCB	Southwest	I-IG-8-2(44)	1970	2	19	3	10	32	0	76	0	0	4	600	35	58		81.2	Good	NHS
ADOT	06496	8		117.8	RCB	Southwest	I-IG-8-2(44)	1970	2	19	5	10	62	30	76	0	0	0		83	99		82.4	Good	NHS
ADOT	06497	8		117.84	RCB	Southwest	I-IG-8-2(44)	1970	2	19	4	12	59	30	76	0	0	2		83	99		82.4	Good	NHS
ADOT	06498	8		117.95	RCB	Southwest	I-IG-8-2(44)	1970	2	19	6	10	91	45	76	0	0	0		41	69		82.4	Good	NHS
ADOT	06499	8		118.1	RCB	Southwest	I-IG-8-2(44)	1970	2	19	3	10	37	30	76	0	0	0		42	70		82.4	Good	NHS
ADOT	00443	8	B	118.15	Wash Bridge	Southwest	FI-56(3)	1955	2	1	3	22	60	0	38	40	0	6	611	24	41		84.6	Fair	NHS
ADOT	06500	8		118.18	RCB	Southwest	I-IG-8-2(44)	1970	2	19	3	10	37	30	76	0	0	2		42	70		82.4	Good	NHS
ADOT	00702	8	B	118.23	State Rte 85 OP	Southwest	S-222-22	1962	2	1	3	43	103	0	38	52	14.72	2	911	36	60		94.9	Fair	NHS
ADOT	01345	8		119.42	E Gila Bend TI UP	Southwest	I-IG-8-2(44)	1969	2	6	2	137	280	30	40	40	17.12		111	49	81		93.3	Fair	NHS
ADOT	06491	8	B	119.75	Sand Tank Wash RCB	Southwest	F-002-2(502)	1964	2	19	2	12	25	0	64	0	0	0		46	76		78.9	Good	NHS
ADOT	00444	8	B	119.76	Sand Tank Wash Br	Southwest	FAP-53-REO	1928	2	1	6	18	108	0	64	64.5	0	3	911	24	41		83.6	Fair	NHS
ADOT	04441	8	B	119.92	RCB	Southwest	FA-53-REO1	1929	2	19	6	10	65	0	64	0	0			41	69		80.6	Fair	NHS
ADOT	00465	8	B	120.25	Gillespie Canal Br	Southwest	F-159(3)	1956	2	1	3	22	61	25	64	76	0	2	911	24	41		85.3	Fair	NHS
ADOT	00118	8	B	120.46	SPRR OP EB	Southwest	NRS-100B-(2)	1934	3	3	3	45	149	30	22	24	21.74	2	911	32	54	F	91.7	Fair	NHS
ADOT	02966	8	B	120.46	UPRR OP	Southwest	085-B(203)A	2012	6	2	3	110	334	30	62	62	23.62		911	38	99		96.0	Good	NHS
ADOT	05275	8		122.03	RCB	Southwest	I-002-2(8)	1959	2	19	2	10	24	30	76	0	0	2		40	67		82.5	Good	NHS
ADOT	06492	8	B	122.18	RCB	Southwest	F-102-2(1)	1959	2	19	3	10	32	0	35	34.6	0	2	600	36	60		97.1	Good	NHS
ADOT	05277	8		134.73	RCB	Southwest	I-002-2(12)	1958	2	19	2	10	21	0	76	0	0		80	99		82.5	Good	NHS	
ADOT	05279	8		136	RCB	Southwest	I-002-2(12)	1958	2	19	3	10	37	30	76	0	0	0		82	99		68.7	Good	NHS
ADOT	05281	8		136.3	RCB EB	Southwest	I-002-2(12)	1958	2	19	8	10	86	0	38	0	0		99	99		97.8	Good	NHS	
ADOT	05282	8		136.3	RCB WB	Southwest	I-002-2(12)	1958	2	19	8	10	86	0	38	0	0		83	99		97.8	Good	NHS	
ADOT	05283	8		137.1	RCB	Southwest	I-002-2(12)	1958	2	19	3	10	32	0	76	0	0	0		43	72		82.5	Good	NHS
ADOT	05285	8		137.5	RCB	Southwest	I-8-2(12)	1958	2	19	3	10	32	0	36	0	0	0	-00	42	70		69.3	Good	NHS
ADOT	05287	8		137.84	RCB	Southwest	I-8-2(12)	1958	2	19	4	10	43	0	76	0	0	0	0	34	57		68.7	Good	NHS
ADOT	05289	8		138.2	RCB	Southwest	I-8-2(12)	1958	2	19	2	10	21	0	76	0	0	0		42	71		69.3	Good	NHS
ADOT	05291	8		139.26	RCB	Southwest	I-8-2(4)	1958	2	19	4	10	43	0	76	0	0	0		40	67		69.3	Good	NHS
ADOT	00533	8		140.8	Freeman TI OP EB	Southwest	I-002-2(4)	1958	1	7	1	26	29	0	38	38	14.62	8	610	32	54	F	90.0	Good	NHS
ADOT	00534	8		140.8	Freeman TI OP WB	Southwest	I-002-2(4)	1958	1	7	1	26	29	0	38	38	14.22	8	610	32	54	F	90.0	Good	NHS
ADOT	05293	8		141.72	RCB EB	Southwest	I-8-2(4)	1959	2	19	6	12	74	30	38	38.4	0	6	611	36	61		97.8	Good	NHS
ADOT	05294	8		141.72	RCB WB	Southwest	I-8-2(4)	1959	2	19	6	12	74	30	38	38.4	0	6	611	36	61		97.8	Good	NHS
ADOT	05295	8		141.85	RCB	Southwest	I-8-2(4)	1959	2	19	3	10	32	0	76	0	0	0		42	70		69.3	Good	NHS
ADOT	05297	8		142.53	RCB EB	Southwest	I-8-2(4)	1959	2	19	6	10	65	0	38	38.2	0	6	611	35	59		97.6	Good	NHS
ADOT	05298	8		142.53	RCB WB	Southwest	I-8-2(4)	1959	2	19	6	10	65	0	38	38.2	0	6	611	35	59		97.7	Good	NHS
ADOT	05299	8		143.69	RCB	Southwest	I-8-2(11)	1959	2	19	2	10	21	0	76	0	0	0		42	71		69.3	Good	NHS
ADOT	05301	8		144.31	RCB EB	Southwest	I-8-2(11)	1959	2	19	8	12	100	30	38	38.3	0	4	611	33	55		96.5	Good	NHS
ADOT	05302	8		144.31	RCB WB	Southwest	I-8-2(11)	1959	2	19	8	12	100	30	38	40.1	0	6	611	33	55		96.6	Good	NHS
ADOT	00550	8		144.55	Vekol Road TI UP	Southwest	I-002-2(11)	1959	4	2	4	85	240	0	26	26	16.22		600	24	41	F	74.6	Fair	NHS
ADOT	00422	8		144.74	Vekol Wash Bridge WB	Southwest	NFA-152(54)B	1954	4	2	3	71	188	0	40	40	0	2	911	33	56		96.5	Fair	NHS
ADOT	00552	8		144.74	Vekol Wash Bridge EB	Southwest	I-002-2(11)	1959	4	2	3	71	190	0	48	48.1	0	1	911	44	73		97.8	Fair	NHS
ADOT	05303	8		145.91	RCB	Southwest	I-8-2(11)	1959	2	19	2	12	24	30	76	0	0	0		82	99		69.3	Good	NHS
ADOT	05305	8		146.74	RCB EB	Southwest	I-8-2(11)	1959	2	19	6	12	74	30	38	0	0	0		90	99		97.8	Good	NHS
ADOT	05306	8		146.74	RCB WB	Southwest	I-8-2(11)	1959	2	19	6	12	74	30	38	0	0	0		90	99		97.8	Good	NHS
ADOT	00619	10	.01		Ehrenberg Bridge	Southwest		1960	3	2	5	246	1113	15	47	94	16.995	0	911	38	67		81.5	Good	NHS
ADOT	01704	10	.62		Poston Rd TI UP	Southwest	I-10-1(21)	1977	4	2	2	99	198	0	44	44	16.37	0	911	43	72		95.5	Fair	NHS
ADOT	05358	10	1.29		RCB	Southwest	FL-1(3)	1949	2	19	3	10	32	0	76	0	0	0		42	70		68.3	Good	NHS
ADOT	05359	10	1.77		Cinnabar Wash RCB EB	Southwest	F1-1(3)	1949	2	19	8	10	86	0	38	38	0	6	600	36	61		96.1	Good	NHS
ADOT	05360	10	1.77		Cinnabar Wash RCB WB	Southwest	I-10-1(8)	1963	2	19	8	10	86	0	38	0	0	0		99	99		97.2	Fair	NHS
ADOT	05361	10	2.83		RCB	Southwest	F1-1(3)	1949	2	19	4	10	43	0	76	0	0	0		79	99		68.3	Fair	NHS
ADOT	05363	10	4.13		RCB EB	Southwest	F1-1(3)	1949	2	19	9	10	98	0	38	0	0	0		40	67		97.2	Good	NHS
ADOT	05364	10	4.13		RCB WB	Southwest	I-10-1(8)	1963	2	19	9	10	112	30	38	0	0	0		99	99		97.2	Good	NHS
ADOT	00767	10	5.84		Tom Wells Rd TI UP	Southwest	I-10-11(18)2	1963	4	2	4	77	247	0	28	28	16.11	0	311	36	58	F	85.2	Fair	NHS
ADOT	05365	10	6.96		La Paz Arroyo RCB EW	Southwest	F1-1(3)	1949	2	19	4	12	59	99	76	0	0	0		42	71		68.3	Good	NHS
ADOT	05367	10	8.16		Gonzales Wash RCB WB	Southwest	FI-98(16)	1950	2	19	5	12	74	30	38	38.1	0	2	611	35	59		97.2	Good	NHS
ADOT	05368	10	8.49		Gonzales Wash RCB EB	Southwest	I-10-1(20)	1950	2	19	2	10	21	0	38	0	0	0		99	99		97.3	Good	NHS
ADOT	05369	10	8.6		Gonzales Wash RCB EB	Southwest	I-10-1(20)	1950	2	19	2	10	21	0	38	0	0	0		99	99		97.3	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS	
ADOT	05370	10		8.83	Gonzales Wash RCB WB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	38	0	0	0		81	99		97.4	Good	NHS	
ADOT	05371	10		9.33	Gonzales Wash RCB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	76	0	0	0		99	99		68.3	Good	NHS	
ADOT	05373	10		9.52	Gonzales Wash RCB	Southwest	I-10-1(20)	1950	2	19	4	12	72	45	76	0	0	0		99	99		68.3	Good	NHS	
ADOT	05375	10		9.83	Gonzales Wash RCB EW	Southwest	I-10-1(20)	1950	2	19	4	12	59	30	76	0	0	0		99	99		68.3	Good	NHS	
ADOT	05378	10		9.99	RCB	Southwest	I-10-1(20)	1963	2	19	2	10	21	0	76	0	0	0		99	99		68.3	Good	NHS	
ADOT	05379	10		10.17	Gonzales Wash RCB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	76	0	0	0		99	99		68.3	Fair	NHS	
ADOT	05381	10		10.29	Gonzales Wash RCB EW	Southwest	FI-98(16)	1950	2	19	3	12	54	45	76	0	0	0		46	77		68.3	Fair	NHS	
ADOT	05383	10		11.11	RCB	Southwest	FI-98(16)	1932	2	19	2	10	21	0	76	0	0	0	-	41	69		75.1	Good	NHS	
ADOT	00755	10		11.95	Dome Rock TI OP EB	Southwest	I-10-1(15)	1963	2	1	3	33	90	0	38	38	14.14	3	911	36	61		95.0	Good	NHS	
ADOT	00756	10		11.95	Dome Rock TI OP WB	Southwest	I-10-1(15)	1963	2	1	3	33	90	0	38	38	14.82	3	911	36	61		95.0	Good	NHS	
ADOT	05385	10		12.64	RCB	Southwest	FI-98(16)	1953	2	19	2	10	21	99	76	0	0	0	-	99	99		75.5	Good	NHS	
ADOT	05387	10		13.96	RCB	Southwest	FI-98(16)	1963	2	19	3	8	27	0	76	0	0	0	-	99	99		75.5	Good	NHS	
ADOT	05389	10		15.16	RCB	Southwest	FI-98(20)	1953	2	19	3	10	32	99	76	0	0	0	-	99	99		75.5	Good	NHS	
ADOT	05391	10		16.24	La Cholla Wash RCB E	Southwest	FI-98(20)	1953	2	19	9	10	98	0	38	39.2	0	2	911	32	54		95.4	Fair	NHS	
ADOT	05392	10		16.24	La Cholla Wash RCB W	Southwest	I-10-1(15)	1963	2	19	9	10	97	0	38	0	0	0	-	99	99		97.4	Good	NHS	
ADOT	00826	10		17.5	West Quartzsite TI UP	Southwest	I-10-1(5)	1964	4	2	4	78	249	0	28	28	15.98	0	311	37	62	F	76.0	Fair		
ADOT	05393	10		17.78	RCB & SFR	Southwest	I-10-1(5)	1964	2	19	3	10	37	30	76	0	0	0	-	86	99		74.3	Good	NHS	
ADOT	05218	10	B	17.92	RCB	Southwest	FA-98(G)	1933	2	19	2	10	21	12	68	0	0	5	600	35	58		78.3	Good	NHS	
ADOT	00813	10		18.09	Quartzsite Ped OP	Southwest	I-10-1(5)	1964	4	2	2	78	299	0	0	5	16.68	0	6	0	0		-2.0	Good	NHS	
ADOT	05395	10		18.2	RCB & SFR	Southwest	I-10-1(5)	1964	2	19	3	10	32	0	76	102	0	3	000	35	58		91.9	Good	NHS	
ADOT	05397	10		18.48	RCB	Southwest	I-10-1(5)	1964	2	19	6	10	64	0	76	0	0	0	-	80	99		74.3	Good	NHS	
ADOT	00791	10		18.61	Tyson Wash Bridge EB	Southwest	I-10-1(5)	1964	2	1	14	30	410	0	38	42	0	4	911	38	64		97.2	Fair	NHS	
ADOT	00792	10		18.61	Tyson Wash Bridge WB	Southwest	I-10-1(5)	1964	2	1	14	30	410	0	38	42	0	4	911	38	63		97.2	Fair	NHS	
ADOT	05399	10		18.72	RCB	Southwest	I-10-1(5)	1964	2	19	3	10	37	30	76	0	0	0	-	38	63		74.3	Good	NHS	
ADOT	01451	10		18.89	SR 95 UP	Southwest	AC-NH-063-2(22)P	2001	5	2	2	132	268	10	68	68	17.35		311	36	99		85.0	Fair		
ADOT	07222	10	B	19.55	Plomosa Wash RCB	Southwest	IM-10-1-(88)	2005	2	19	4	10	43	10	68	0	0	0	0	0	34	57		80.5	Good	NHS
ADOT	05401	10		19.56	RCB	Southwest	I-10-1(5)	1964	2	19	4	10	43	0	100	0	0	0	-	42	69		74.3	Good	NHS	
ADOT	07070	10	B	19.76	Plomosa Wash RCB	Southwest	IM-10-1-(88)	2005	2	19	4	10	43	0	68	0	0	0	0	0	34	57		80.5	Good	NHS
ADOT	02726	10		19.9	Riggles Avenue TI UP	Southwest	IM-10-1(88)	2002	5	2	2	130	263	8	68	68	17.37		311	40	99		98.5	Good		
ADOT	05403	10		19.93	RCB	Southwest	I-10-1(5)	1964	2	19	4	10	49	30	140	0	0	0	0	-	83	99		73.1	Good	NHS
ADOT	05405	10		20.83	RCB	Southwest	I-10-1(11)	1960	2	19	4	10	60	45	76	0	0	0	-	79	99		70.0	Good	NHS	
ADOT	05407	10		22.06	RCB	Southwest	I-10-1(11)	1960	2	19	6	10	91	45	76	0	0	0	-	99	99		70.0	Good	NHS	
ADOT	00769	10		26.65	Gold Nugget TI UP	Southwest	I-10-1(19)	1963	4	2	4	78	250	0	26	26	16.1	0	311	36	58	F	93.9	Fair		
ADOT	06103	10		26.8	Italian Wash RCB E&W	Southwest	FA-98-1(19)	1953	2	19	6	10	64	0	80	0	0	0	-	79	99		70.0	Good	NHS	
ADOT	05409	10		28.81	RCB	Southwest	FI-98-1(9)	1953	2	19	6	10	64	0	76	0	0	0	-	79	99		70.0	Fair	NHS	
ADOT	06110	10		30.38	RCB EB	Southwest	I-10-1(24)	1969	2	19	3	9	29	0	38	0	0	0	-	39	64		97.2	Good	NHS	
ADOT	06111	10		30.38	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	25	30	38	0	0	0	-	40	67		97.3	Good	NHS	
ADOT	06108	10		30.68	RCB EB	Southwest	FI-98(19)	1953	2	19	3	10	37	30	41	0	0	0	-	79	99		82.0	Fair	NHS	
ADOT	06109	10		30.68	RCB WB	Southwest	I-10-1(24)	1967	2	19	3	10	37	30	38	0	0	0	-	99	99		82.1	Good	NHS	
ADOT	01201	10		31.17	Brenda TI UP	Southwest	I-10-1(24)	1967	2	6	3	138	377	25	40	30	17.71		111	33	55		82.0	Fair		
ADOT	06200	10		31.5	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	24	30	38	0	0	0	0	0	99	99		82.0	Good	NHS
ADOT	06238	10		31.5	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	24	30	38	0	0	0	-00	84	99		97.2	Good	NHS	
ADOT	06239	10		31.55	RCB EB	Southwest	I-10-1(24)	1969	2	19	6	10	93	45	38	0	0	0	-00	41	69		97.2	Good	NHS	
ADOT	06240	10		31.56	RCB WB	Southwest	I-10-1(24)	1969	2	19	5	10	64	30	38	0	0	0	0	0	82	99		97.1	Good	NHS
ADOT	06241	10		32.5	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	12	25	30	38	0	0	0	-00	99	99		97.2	Good	NHS	
ADOT	06242	10		32.51	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	12	25	30	38	0	0	0	-00	99	99		97.1	Fair	NHS	
ADOT	06243	10		32.55	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0	0	-00	99	99		97.2	Good	NHS	
ADOT	06244	10		32.55	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0	0	-00	99	99		97.1	Good	NHS	
ADOT	01202	10		33.78	Ramsey Mine Rd UP	Southwest	I-10-1(24)	1967	2	6	3	125	330	0	26	26	16.2		111	56	95	F	90.9	Fair		
ADOT	06245	10		33.95	RCB EB	Southwest	I-10-1(24)	1969	2	19	3	12	38	30	38	0	0	0	-00	82	99		96.9	Good	NHS	
ADOT	06246	10		33.95	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	12	38	30	38	0	0	0	-00	82	99		96.9	Good	NHS	
ADOT	06247	10		34.1	RCB EB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0	0	-00	82	99		96.9	Good	NHS	
ADOT	06248	10		34.1	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0	0	-00	41	69		96.9	Good	NHS	
ADOT	06249	10		34.15	RCB EB	Southwest	I-10-1(24)	1969	2	19	4	10	44	0	38	0	0	0	-00	99	99		96.9	Good	NHS	
ADOT	06250	10		34.15	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0	0	-00	79	99		96.9	Good	NHS	
ADOT	06251	10		34.25	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0	0	-00	99	99		96.9	Good	NHS	
ADOT	06252	10		34.25	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0	0	-00	42	71		96.9	Good	NHS	
ADOT	06253	10		35.15	RCB EB	Southwest	I-10-1(24)	1967	2	19	6	10	64	0	38	0	0	0	-00	82	99		96.9	Good	NHS	
ADOT	06254	10		35.15	RCB WB	Southwest	I-10-1(24)	1969	2	19	6	10	64	0	38	0	0	0	-00	41	69		96.9	Good	NHS	
ADOT	06255	10		35.17	RCB WB	Southwest	I-10-1(35)	1974	2	19	3	11	34	20	38	0	0	0	-00	41	69		96.9	Good	NHS	

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
ADOT	06256	10		35.18	RCB EB	Southwest	I-10-1(24)	1967	2	19	3	11	32	20	38	0	0		-00	82	99		96.9	Good	NHS
ADOT	01203	10		37.11	Wash Bridge EB	Southwest	I-10-1(24)	1967	2	1	5	35	164	45	38	38	0	1	911	43	72		96.2	Good	NHS
ADOT	01204	10		37.11	Wash Bridge WB	Southwest	I-10-1(24)	1967	2	1	5	35	164	45	38	38	0	1	110	43	72		95.1	Fair	NHS
ADOT	01205	10		39.37	New Water Mtn Br EB	Southwest	I-10-1(27)	1967	2	1	4	30	111	45	38	38	0	1	110	43	72		95.2	Good	NHS
ADOT	01206	10		39.37	New Water Mtn Br WB	Southwest	I-10-1(27)	1967	2	1	4	30	111	45	38	38	0	2	110	43	72		95.1	Good	NHS
ADOT	06257	10		39.9	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	14	29	45	38	0	0		-00	43	72		96.9	Good	NHS
ADOT	06258	10		39.91	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	14	29	45	38	0	0		-00	43	72		96.9	Good	NHS
ADOT	06259	10		40.24	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	12	24	30	38	0	0		-00	43	72		96.9	Good	NHS
ADOT	06260	10		40.25	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	12	24	30	38	0	0		-00	43	72		96.9	Good	NHS
ADOT	06261	10		42.8	RCB EB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0		-00	49	82		96.9	Good	NHS
ADOT	06262	10		42.8	RCB WB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0		-00	49	82		96.9	Fair	NHS
ADOT	06263	10		42.95	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Good	NHS
ADOT	06264	10		42.95	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Good	NHS
ADOT	06265	10		43.05	RCB EB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0		-00	49	82		96.9	Good	NHS
ADOT	06266	10		43.05	RCB WB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0		-00	49	82		96.9	Good	NHS
ADOT	06267	10		43.4	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	10	32	0	38	0	0		-00	38	63		96.9	Good	NHS
ADOT	06268	10		43.4	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	10	32	0	38	0	0		-00	38	63		96.9	Good	NHS
ADOT	06269	10		43.65	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Good	NHS
ADOT	06270	10		43.65	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Good	NHS
ADOT	06271	10		43.95	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	49	82		96.9	Good	NHS
ADOT	06272	10		43.95	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	49	82		96.9	Good	NHS
ADOT	06273	10		44.2	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Fair	NHS
ADOT	06274	10		44.2	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0		-00	48	81		96.9	Fair	NHS
ADOT	01207	10		45.34	Vicksburg Rd TI UP	Southwest	I-10-1(27)	1967	2	6	3	127	332	10	34	32.4	15.9		911	47	79	F	91.8	Fair	
ADOT	06275	10		48.2	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	10	21	0	38	0	0		-00	40	67		97.0	Good	NHS
ADOT	06276	10		48.2	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	10	21	0	38	0	0		-00	40	67		97.1	Fair	NHS
ADOT	06277	10		51.75	RCB EB	Southwest	I-10-1(30)	1970	2	19	3	10	32	0	38	0	0		-00	42	70		97.0	Good	NHS
ADOT	06278	10		51.75	RCB WB	Southwest	I-10-1(30)	1970	2	19	3	10	32	0	38	0	0		-00	83	99		97.1	Good	NHS
ADOT	01410	10		52.24	CAP Canal Br WB	Southwest		1982	6	2	2	73	152	17	66	65.1	0	1	911	42	99		97.2	Good	NHS
ADOT	01409	10		52.25	CAP Canal Br EB	Southwest		1982	6	2	2	65	137	17	77	77.4	0	1	911	41	72		97.1	Good	NHS
ADOT	01384	10		53.94	Hovatter Rd TI UP	Southwest	I-10-1(30)	1970	2	6	3	125	352	0	40	40	16.24		111	45	75		96.9	Good	NHS
ADOT	01411	10		54.34	CAP Canal Br EB	Southwest		1982	5	2	1	92	96	22	50	50	0	1	911	36	99		97.2	Good	NHS
ADOT	01412	10		54.35	CAP Canal Br WB	Southwest		1982	5	2	1	92	96	22	42	42	0	1	911	38	99		97.2	Good	NHS
ADOT	01414	10		59.15	CAP Canal Br WB	Southwest		1982	5	2	1	103	107	30	42	42	0	1	911	46	99		97.2	Good	NHS
ADOT	01413	10		59.16	CAP Canal Br EB	Southwest		1982	5	2	1	103	107	30	42	42	0	1	911	46	99		97.2	Good	NHS
ADOT	01282	10		59.47	Sore Finger Rd UP	Southwest	I-10-1(33)	1968	2	6	3	125	330	0	26	26	16.58		111	49	83		100.0	Fair	
ADOT	06205	10		65.6	RCB WB	Southwest	I-10-1(33)	1968	2	19	2	10	21	0	38	0	0		-00	80	99		97.2	Good	NHS
ADOT	06204	10		65.61	RCB EB	Southwest	I-10-1(33)	1968	2	19	2	10	21	0	38	0	0		-00	80	99		97.2	Good	NHS
ADOT	06281	10		67.55	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0		-00	99	99		97.2	Good	NHS
ADOT	06282	10		67.55	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0		-00	99	99		97.2	Good	NHS
ADOT	06283	10		67.6	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06284	10		67.6	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06207	10		67.67	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06286	10		67.67	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06208	10		67.72	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06288	10		67.72	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06289	10		67.77	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06290	10		67.77	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06206	10		67.82	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06292	10		67.82	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06209	10		67.87	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06294	10		67.87	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06210	10		67.95	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06296	10		67.95	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06297	10		68.05	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06298	10		68.05	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06299	10		68.1	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06300	10		68.1	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS
ADOT	06211	10		69.2	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0			42	70		97.2	Good	NHS
ADOT	06212	10		69.2	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0			85	99		97.2	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS	
ADOT	06213	10		69.3	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0			85	99		97.2	Good	NHS	
ADOT	06214	10		69.3	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	50	0	0			85	99		82.0	Fair	NHS	
ADOT	06215	10		69.4	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	48	0	0			85	99		97.2	Good	NHS	
ADOT	06216	10		69.4	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	60	0	0			85	99		82.0	Good	NHS	
ADOT	01283	10		69.66	Ave 75 E TI UP	Southwest	I-10-1(33)	1968	2	6	3	127	331	10	28	28.8	16.19		911	55	93		93.2	Fair		
ADOT	06217	10		70.5	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06218	10		70.5	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.3	Good	NHS	
ADOT	06219	10		70.53	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06220	10		70.53	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.3	Good	NHS	
ADOT	06221	10		70.56	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06222	10		70.56	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.3	Good	NHS	
ADOT	06223	10		70.59	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06224	10		70.59	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.2	Good	NHS	
ADOT	06225	10		70.62	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06226	10		70.62	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.3	Good	NHS	
ADOT	06227	10		70.65	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06228	10		70.65	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06229	10		70.68	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	06230	10		70.68	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.3	Good	NHS	
ADOT	06231	10		70.7	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Fair	NHS	
ADOT	06232	10		70.7	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0			99	99		97.1	Good	NHS	
ADOT	01208	10		72.71	Eagle Eye Road UP	Southwest	I-10-2(7)	1967	2	6	3	126	331	10	26	26	16.33		111	51	86		97.9	Good		
ADOT	06382	10		74.1	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06383	10		74.1	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06384	10		74.12	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06385	10		74.12	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06386	10		74.14	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06387	10		74.14	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06388	10		74.16	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06389	10		74.16	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06390	10		76.2	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06391	10		76.2	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06392	10		76.22	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06393	10		76.22	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06394	10		76.23	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06395	10		76.23	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06396	10		76.25	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06397	10		76.25	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06398	10		76.27	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.2	Good	NHS
ADOT	06399	10		76.27	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0	0			99	99		97.3	Good	NHS
ADOT	06400	10		80.84	RCB WB	Southwest	I-10-2(10)	1968	2	19	10	10	125	30	38	0	0	0			42	70		82.2	Good	NHS
ADOT	06401	10		80.85	RCB EB	Southwest	I-10-2(10)	1968	2	19	10	10	125	30	38	0	0	0			99	99		97.2	Good	NHS
ADOT	01209	10		81.21	Salome Road TI UP	Southwest	I-10-2(10)	1967	2	6	3	143	376	30	28	28	16		111	46	77		97.0	Good		
ADOT	06403	10		81.69	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0	0			79	99		97.3	Good	NHS
ADOT	06402	10		81.7	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	51	0	0	0			38	64		82.0	Good	NHS
ADOT	06405	10		81.75	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0	0			79	99		97.3	Good	NHS
ADOT	06404	10		81.76	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	46	0	0	0			38	64		97.1	Good	NHS
ADOT	06407	10		81.8	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0	0	-00		79	99		97.3	Good	NHS
ADOT	06406	10		81.81	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	44	0	0	0			38	64		97.1	Good	NHS
ADOT	06408	10		81.96	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0			82	99		97.1	Good	NHS
ADOT	06409	10		81.96	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00		82	99		97.3	Good	NHS
ADOT	06410	10		82.05	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0			83	99		97.1	Good	NHS
ADOT	06411	10		82.05	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00		83	99		97.3	Good	NHS
ADOT	06412	10		82.15	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0			84	99		97.1	Good	NHS
ADOT	06413	10		82.15	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00		42	70		97.3	Good	NHS
ADOT	06414	10		82.25	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0			42	70		97.1	Good	NHS
ADOT	06415	10		82.25	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00		42	70		97.3	Good	NHS
ADOT	06416	10		82.5	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0	0			41	69		97.1	Good	NHS
ADOT	06417	10		82.5	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0	0	-00		41	69		97.3	Good	NHS
ADOT	06418	10		82.7	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	23	30	38	0	0	0			84	99		97.1	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
ADOT	06419	10		82.71	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0	0	-00	84	99		97.3	Good	NHS
ADOT	06420	10		83.25	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0		83	99		97.1	Good	NHS
ADOT	06421	10		83.25	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00	83	99		97.3	Good	NHS
ADOT	06422	10		84.38	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0		84	99		97.1	Good	NHS
ADOT	06423	10		84.38	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00	84	99		97.3	Good	NHS
ADOT	06424	10		84.43	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0		42	70		97.1	Good	NHS
ADOT	06425	10		84.43	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0	0	-00	42	70		97.3	Good	NHS
ADOT	06426	10		85.49	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0			84	99		97.1	Good	NHS
ADOT	06427	10		85.5	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0			84	99		97.3	Good	NHS
ADOT	06428	10		86.8	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0			83	99		97.1	Good	NHS
ADOT	06429	10		86.81	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0			83	99		97.3	Good	NHS
ADOT	06430	10		87.08	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	64	0	38	0	0			41	69		97.1	Fair	NHS
ADOT	06431	10		87.08	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	64	0	38	0	0			41	69		97.3	Good	NHS
ADOT	06433	10		88.09	Tenneman Wash RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0			99	99		97.3	Good	NHS
ADOT	06432	10		88.1	Tenneman Wash RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0			42	71		97.1	Good	NHS
ADOT	06435	10		89.2	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0			42	70		97.3	Fair	NHS
ADOT	06434	10		89.21	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0			42	70		97.1	Good	NHS
ADOT	06436	10		89.4	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0			41	69		97.1	Good	NHS
ADOT	06437	10		89.4	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0			99	99		97.3	Good	NHS
ADOT	06439	10		89.55	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0			84	99		97.3	Good	NHS
ADOT	06438	10		89.56	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0			42	70		97.1	Good	NHS
ADOT	06441	10		90.4	RCB WB	Southwest	I-10-2(10)	1968	2	19	4	10	49	30	38	0	0			99	99		97.3	Fair	NHS
ADOT	06440	10		90.41	RCB EB	Southwest	I-10-2(10)	1968	2	19	4	10	49	30	38	0	0			99	99		97.1	Fair	NHS
ADOT	06442	10		90.82	RCB EB	Southwest	I-10-2(13)	1970	2	19	6	10	64	0	38	0	0			42	70		97.1	Good	NHS
ADOT	06443	10		90.82	RCB WB	Southwest	I-10-2(13)	1970	2	19	6	10	64	0	38	0	0		-00	83	99		97.3	Fair	NHS
ADOT	06445	10		91.95	RCB WB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	38	0	0	4	-00	99	99		97.3	Good	NHS
ADOT	06444	10		91.97	RCB EB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	38	0	0	4	-00	99	99		97.1	Fair	NHS
ADOT	06446	10		93.12	RCB EB	Southwest	I-10-2(13)	1970	2	19	3	10.187	33	11	38	0	0	4	-00	99	99		97.1	Good	NHS
ADOT	06447	10		93.12	RCB WB	Southwest	I-10-2(13)	1970	2	19	3	10.187	33	11	38	0	0	4	-00	42	70		97.3	Good	NHS
ADOT	06448	10		93.77	RCB	Southwest	I-10-2(13)	1970	2	19	6	11.547	74	30	152	0	0	4	-00	99	99		70.0	Fair	NHS
ADOT	01523	10		94.15	411th Ave TI UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	40	40	16.58		111	56	93		99.7	Fair	NHS
ADOT	06449	10		94.25	RCB	Southwest	I-10-2(13)	1970	2	19	2	14.142	29	45	152	0	0	4	-00	99	99		70.0	Good	NHS
ADOT	06450	10		94.3	RCB Ramp B	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	23	0	0	4	-00	99	99		97.8	Good	NHS
ADOT	06451	10		94.85	RCB North Frnt Road	Southwest	I-10-2(13)	1970	2	19	3	12	37	30	26	0	0	2	-00	46	77		99.8	Fair	NHS
ADOT	06452	10		94.9	RCB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	152	0	0	2	-00	38	63		70.0	Fair	NHS
ADOT	01524	10		95.3	Old Camp Wash Br WB	Southwest	I-10-2(13)	1971	2	1	3	35	94	0	38	38	0	2	110	40	67		95.1	Fair	NHS
ADOT	01525	10		95.3	Old Camp Wash Br EB	Southwest	I-10-2(13)	1971	2	1	3	35	94	0	38	38	0	2	110	40	66		95.1	Fair	NHS
ADOT	01526	10		96.21	Belmont Rd UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	28	28	16.95		111	31	52		97.1	Fair	NHS
ADOT	01527	10		96.53	Coyote Wash Br WB	Southwest	I-10-2(13)	1971	2	1	3	40	107	0	38	38	0	1	110	36	61		94.1	Good	NHS
ADOT	01528	10		96.53	Coyote Wash Br EB	Southwest	I-10-2(13)	1971	2	1	3	40	107	0	38	38	0	2	110	36	61		94.0	Good	NHS
ADOT	06453	10		96.75	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	4	-00	80	99		70.0	Good	NHS
ADOT	06454	10		97.7	RCB	Southwest	I-10-2(13)	1970	2	19	3	10	32	0	152	0	0	4	-00	42	70		70.0	Fair	NHS
ADOT	06455	10		98.2	Four Mile Wash RCB	Southwest	I-10-2(13)	1970	2	19	4	10	43	0	152	0	0	4	-00	79	99		70.0	Fair	NHS
ADOT	06724	10		98.25	Ramp A RCB	Southwest	I-10-2(503)	1980	2	19	5	10	53	0	22	0	0	4	-00	83	99		97.7	Good	NHS
ADOT	06726	10		98.25	Ramp C RCB	Southwest	I-10-2(503)	1980	2	19	5	10	53	0	22	0	0	4	-00	80	99		97.6	Good	NHS
ADOT	01529	10		98.29	Wintersburg Rd TI UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	28	28	16.4		111	56	94		90.1	Fair	NHS
ADOT	06592	10		98.3	Wintersburg Road RCB	Southwest	I-10-2(13)	1970	2	19	2	14.142	29	45	28	0	0	4	-00	99	99		98.0	Good	NHS
ADOT	06456	10		98.35	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	4	-00	41	69		70.0	Good	NHS
ADOT	06725	10		98.35	RCB Ramp B	Southwest	I-10-2(503)	1980	2	19	5	8	43	0	26	0	0	4	-00	49	82		95.0	Good	NHS
ADOT	06457	10		99.15	RCB EB	Southwest	I-10-2(13)	1970	2	19	5	10	53	0	38	0	0	-00	83	99		97.0	Good	NHS	
ADOT	06458	10		99.15	RCB WB	Southwest	I-10-2(13)	1970	2	19	5	10	53	0	38	0	0	-00	99	99		97.1	Fair	NHS	
ADOT	06459	10		100.23	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	-00	99	99		71.6	Good	NHS	
ADOT	06564	10		101.35	RCB	Southwest	I-10-2(16)	1974	2	19	2	10	21	0	152	0	0	-00	80	99		71.6	Good	NHS	
ADOT	01647	10		101.4	355th Ave UP	Southwest	I-10-2(16)	1974	2	6	2	125	253	15	26	26	16.04		111	53	89		98.0	Fair	NHS
ADOT	06565	10		101.51	RCB	Southwest	I-10-2(16)	1974	2	19	2	10	21	0	152	0	0	-00	99	99		71.6	Good	NHS	
ADOT	06566	10		101.66	RCB	Southwest	I-10-2(16)	1974	2	19	3	10	32	0	152	0	0	-00	99	99		71.6	Good	NHS	
ADOT	01644	10		103.44	339th Avenue TI UP	Southwest	I-10-2(16)	1974	2	6	2	125	253	15	28	28	16.49		111	64	99		81.1	Fair	NHS
ADOT	06567	10		104.34	RCB	Southwest	I-10-2(16)	1974	2	19	4	10	43	0	152	0	0	-00	85	99		70.8	Good	NHS	
ADOT	01645	10		104.69	Hassayampa Rvr Br WB	Southwest	I-10-2(16)	1974	6	2	15	79	1180	10	38	42	0		911	36	88		97.0	Good	NHS
ADOT	01646	10		104.69	Hassayampa Rvr Br EB	Southwest	I-10-2(16)	1974	6	2	15	79	1180	10	38	42	0		911	36	88		96.9	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
ADOT	01664	10		107.6	Johnson Road UP	Southwest	I-10-2(61)	1975	2	6	2	125	253	15	26	26	16.71		111	58	97		94.3	Fair	
ADOT	02078	10		109.68	Palo Verde Rd TI UP	Southwest	I-10-2-507	1988	6	2	2	133	271	15	104	104	16.75		911	36	59		99.4	Good	
ADOT	06833	10		109.68	Palo Verde Rd RCB	Southwest	I-10-2-507	1988	2	19	4	10	43	0	94	0	0		-00	99	99		83.3	Good	NHS
ADOT	04001	60		31.56	RCB	Southwest	FL-1(A)	1932	2	19	2	10	24	30	41	0	0			42	71		97.8	Good	
ADOT	04002	60		32.83	RCB	Southwest	FL-1(A)	1932	2	19	2	10	29	45	41	48	0	4	0	36	59		94.8	Good	
ADOT	04003	60		34.05	RCB	Southwest	FL-1(A)	1932	2	19	3	10	46	45	42	0	0	2	-	77	99		82.3	Fair	
ADOT	04004	60		34.23	RCB	Southwest	FL-1(A)	1932	2	19	3	10	46	45	41	0	0	0	-00	78	99		97.8	Fair	
ADOT	00085	60		34.44	Wash Bridge	Southwest	FL-1(A)	1932	1	1	2	22	44	0	41	43	0	4	911	26	45		80.6	Fair	
ADOT	00086	60		35.44	Wash Bridge	Southwest	FL-98(F)	1932	1	1	5	22	110	30	40	43	0	4	911	26	45		89.2	Fair	
ADOT	00087	60		35.59	Wash Bridge	Southwest	FA-98(F)	1932	1	1	2	22	44	30	40	43	0	4	911	26	45		89.2	Fair	
ADOT	04005	60		37.14	RCB	Southwest	FA-98(F)	1932	2	19	4	10	43	0	42	48	0	4	0	35	59		94.6	Good	
ADOT	04006	60		41.24	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	4	0	35	58		94.6	Fair	
ADOT	04007	60		41.38	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	8	0	33	55		93.5	Fair	
ADOT	04008	60		41.49	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	8	000	33	55		82.2	Fair	
ADOT	04009	60		41.6	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	8	0	33	55		93.5	Fair	
ADOT	04010	60		41.76	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	000	33	55		93.5	Fair	
ADOT	04011	60		41.85	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	4	0	33	55		82.2	Fair	
ADOT	04012	60		41.98	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	0	33	55		93.5	Fair	
ADOT	04013	60		42.1	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	0	33	55		93.5	Fair	
ADOT	04014	60		42.23	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	0	33	55		82.2	Fair	
ADOT	04015	60		42.36	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	000	33	55		93.5	Fair	
ADOT	04016	60		44.4	RCB	Southwest	FA-98(F)	1932	2	19	2	10	21	0	41	0	0		-00	35	58		97.7	Good	
ADOT	04017	60		45.06	RCB	Southwest	FA-98(F)	1932	2	19	2	10	21	0	40	48	0	6	000	36	58		94.8	Good	
ADOT	04018	60		46.17	RCB	Southwest	FA-98(F)	1932	2	19	3	10	32	0	41	48	0	6	000	35	58		94.5	Good	
ADOT	04019	60		46.36	RCB	Southwest	FA-98(E)	1932	2	19	3	10	32	0	41	48	0	6	000	35	58		94.5	Good	
ADOT	04020	60		46.8	RCB	Southwest	FA-98(E)	1932	2	19	4	10	43	0	41	48	0	6	000	35	58		94.5	Good	
ADOT	01406	60		46.92	US 60 CAP Br (Hope)	Southwest	USBR-DC7344	1978	5	2	1	99	101	33	44	44	0		911	36	99		99.5	Good	
ADOT	04021	60		47.52	RCB	Southwest	FA-98(E)	1932	2	19	2	10	21	0	41	48	0	6	000	36	58		94.6	Good	
ADOT	04022	60		47.94	RCB	Southwest	FA-98(E)	1932	2	19	2	10	21	0	41	48	0	6	000	36	58		94.6	Good	
ADOT	00643	72		32.13	Butler Wash Bridge	Southwest	NS-265(61)A	1961	2	1	4	30	111	0	34	34	0	2	611	27	45		80.1	Good	
ADOT	01405	72		44.1	SR 72 CAP Bridge	Southwest	DC-7298	1978	5	2	1	98	100	31	38	38	0		911	36	98		89.3	Fair	
ADOT	06695	72		44.32	CAP RCB	Southwest	DC-7298	1978	2	19	2	10	30	45	38	0	0		0	42	71		92.0	Good	
ADOT	00734	85		0.37	Gila Bend SPRR UP	Southwest	S-222(22)	1963	3	2	3	44	106	0	0	31	15.55	0	300	61	99		-2.0	Good	
ADOT	04553	85		0.55	RCB	Southwest	S-222(22)	1962	2	19	3	12	37	30	40	0	0		0	99	99		99.7	Fair	
ADOT	00735	85		.65	Gillespie Canal Br	Southwest	S-222(22)	1963	5	5	1	55	56	8	40	40	0	1	311	38	82		82.1	Fair	
ADOT	04554	85		2.77	RCB	Southwest	S-222(22)	1962	2	19	2	12	24	30	38	0	0		0	83	99		82.3	Good	
ADOT	04555	85		3.35	Quilotosa Wash RCB	Southwest	S-222(15)	1958	2	19	8	10	87	0	34	39.2	0	4	600	35	59		81.5	Good	
ADOT	04556	85		5.01	RCB	Southwest	S-222(15)	1958	2	19	2	12	24	30	34	39.6	0	4	600	36	60		81.7	Fair	
ADOT	04557	85		5.28	RCB	Southwest	S-222(15)	1958	2	19	7	12	88	30	34	39.2	0	4	600	35	59		81.5	Fair	
ADOT	04558	85		6.03	RCB	Southwest	S-222(19)	1959	2	19	3	10	32	0	34	39.2	0	4	600	35	58		81.5	Good	
ADOT	04559	85		6.49	RCB	Southwest	S-222(19)	1959	2	19	4	10	43	0	34	39.1	0	4	600	32	53		79.4	Good	
ADOT	04560	85		8.35	RCB	Southwest	S-222(19)	1959	2	19	2	10	21	0	34	0	0		0	99	99		84.7	Good	
ADOT	04561	85		8.94	RCB	Southwest	S-222(19)	1959	2	19	3	10	32	0	34	39.1	0	4	600	35	59		81.5	Good	
ADOT	04562	85		10.63	RCB	Southwest	S-222(21)	1960	2	19	2	10	21	0	36	0	0		0	42	71		84.7	Good	
ADOT	04563	85		10.89	RCB	Southwest	S-222(21)	1960	2	19	6	10	65	0	36	49.6	0	4	000	32	53		79.4	Good	
ADOT	04564	85		11.22	RCB	Southwest	S-222(21)	1960	2	19	2	14	30	45	36	46.5	0	6	000	36	58		77.8	Fair	
ADOT	04565	85		11.97	RCB	Southwest	S-222(21)	1960	2	19	2	10	21	0	34	0	0		0	40	67		84.7	Good	
ADOT	04566	85		12.2	RCB	Southwest	S-222(21)	1960	2	19	3	10	32	0	36	0	0		0	38	64		84.7	Good	
ADOT	04567	85		12.52	RCB	Southwest	S-222(21)	1960	2	19	4	10	43	0	34	0	0		0	39	66		84.7	Good	
ADOT	04568	85		12.83	RCB	Southwest	S-222(21)	1960	2	19	4	10	43	0	38	0	0		0	79	99		80.0	Good	
ADOT	04569	85		15.24	RCB	Southwest	S-222(21)	1960	2	19	3	10	32	0	35	42.1	0	4	000	36	59		81.7	Good	
ADOT	04570	85		17.3	RCB	Southwest	S-222(505)	1967	2	19	5	10	53	0	35	44.2	0	4	000	35	59		81.5	Good	
ADOT	04571	85		17.67	RCB	Southwest	S-222(505)	1967	2	19	2	10	21	0	35	0	0		0	43	72		84.7	Good	
ADOT	04572	85		19.05	RCB	Southwest	S-222(505)	1967	2	19	2	10	21	0	35	0	0		0	43	72		84.7	Good	
ADOT	04573	85		20.54	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	24	30	27	33.5	0	4	000	36	59		76.6	Fair	
ADOT	04574	85		23.46	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	21	0	26	28.1	0	4	000	36	59		69.2	Good	
ADOT	04575	85		23.84	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	21	0	25	28.1	0	4	000	36	58		72.1	Good	
ADOT	04576	85		23.95	RCB	Southwest	WPS-120	1937	2	19	3	10	32	0	25	28.2	0	4	000	35	59		71.9	Good	
ADOT	00176	85		27.23	Midway Wash Bridge	Southwest	FLH-10A-1	1937	2	1	4	25	101	0	28	24	0	3	400	30	50		58.2	Fair	
ADOT	04577	85		28.6	RCB	Southwest	WPS-120	1937	2	19	3	10	32	0	41	85	0	361	000	35	59		81.5	Fair	

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
ADOT	04442	85		120.85	RCB	Southwest	F-159(3)	1956	2	19	3	10	33	14	45	0	0	0		38	64		69.8	Good	NHS
ADOT	04443	85		123.84	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911	33	55		98.4	Good	NHS
ADOT	07154	85		123.86	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	10	43	0	0	0		33	56		98.4	Good	NHS
ADOT	04444	85		123.91	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911	33	55		98.4	Good	NHS
ADOT	07155	85		123.93	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	5	43	0	0	0		82	99		99.7	Good	NHS
ADOT	07156	85		124.29	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	2	11	23	25	43	0	0	0		82	99		99.7	Good	NHS
ADOT	04445	85		125.14	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	44	0	2	911	35	59		99.5	Good	NHS
ADOT	07157	85		125.16	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	65	0	43	0	0	0		41	69		99.7	Good	NHS
ADOT	04446	85		125.5	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911	33	55		98.4	Good	NHS
ADOT	07158	85		125.52	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	0	43	0	0	0		33	56		98.4	Good	NHS
ADOT	04447	85		125.65	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	43.8	0	2	911	35	59		99.5	Good	NHS
ADOT	07159	85		125.66	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	65	0	43	0	0	0		41	69		99.7	Good	NHS
ADOT	07160	85		125.95	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	67	15	43	0	0	0		84	99		99.7	Good	NHS
ADOT	04448	85		126.22	RCB NB	Southwest	F-159(3)	1956	2	19	3	10	32	0	40	43.9	0	2	911	35	59		99.5	Good	NHS
ADOT	07121	85		126.22	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	3	10	32	0	43	0	0	0		42	70		99.7	Good	NHS
ADOT	07122	85		126.58	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0		83	99		99.7	Good	NHS
ADOT	07123	85		126.74	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	22	20	43	0	0	0		42	71		99.7	Good	NHS
ADOT	07124	85		126.8	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0		83	99		99.7	Good	NHS
ADOT	07125	85		126.84	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	12	24	30	43	0	0	0		82	99		99.7	Good	NHS
ADOT	04449	85		127.15	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	43.9	0	2	911	35	59		99.5	Good	NHS
ADOT	07126	85		127.15	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	6	10	65	0	43	0	0	0		83	99		99.7	Good	NHS
ADOT	07127	85		127.56	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0		84	99		99.7	Good	NHS
ADOT	04450	85		128.44	RCB NB	Southwest	F-159(2)	1956	2	19	3	10	32	0	40	44	0	2	911	36	59		99.7	Good	NHS
ADOT	07128	85		128.44	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	3	10	32	5	43	0	0	0		83	99		99.7	Good	NHS
ADOT	07129	85		128.89	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0		40	67		99.7	Good	NHS
ADOT	07130	85		128.94	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	10	43	0	0	0		99	99		99.7	Good	NHS
ADOT	04451	85		129.88	RCB NB	Southwest	F-159(2)	1956	2	19	2	10	21	0	40	44.1	0	2	911	36	59		99.7	Good	NHS
ADOT	07131	85		129.88	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	4	10	43	0	43	0	0	0		82	99		99.7	Good	NHS
ADOT	04452	85		130.01	RCB NB	Southwest	F-159(2)	1956	2	19	2	10	21	0	40	44.2	0	2	911	36	60		99.7	Good	NHS
ADOT	07132	85		130.01	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	3	10	32	5	43	0	0	0		78	99		99.7	Good	NHS
ADOT	07243	85		131.18	RCB	Southwest	NH-085-B(011)	2009	2	19	4	10	41	13	84	0	0	0		39	66		70.0	Good	NHS
ADOT	04453	85		131.99	RCB	Southwest	F-159(2)	1956	2	19	5	10	55	8	84	0	0	0		79	99		70.0	Good	NHS
ADOT	04454	85		132.35	RCB	Southwest	F-159(2)	1956	2	19	4	10	43	0	78	0	0	0		82	99		69.8	Good	NHS
ADOT	07192	85		133.01	RCB SB	Southwest	085-B(011)	2009	2	19	2	10	21	0	38	0	0	0		42	71		99.7	Good	NHS
ADOT	07201	85		133.01	RCB WFR	Southwest	085-B(011)	2009	2	19	2	10	21	0	32	0	0	0		42	71		100.0	Good	
ADOT	07202	85		133.08	RCB WFR	Southwest	085-B(011)	2009	2	19	3	10	34	18	32	0	0	0		42	70		100.0	Good	
ADOT	07193	85		133.1	RCB	Southwest	085-B(011)	2009	2	19	3	11	36	27	78	0	0	0		42	70		84.2	Good	NHS
ADOT	07203	85		133.74	RCB WFR	Southwest	085-B(011)	2009	2	19	3	10	32	0	32	0	0	0		82	99		100.0	Good	
ADOT	07195	85		133.78	RCB SB	Southwest	085-B(011)	2009	2	19	3	13	40	37	56	0	0	0		82	99		84.6	Good	NHS
ADOT	07244	85		133.84	RCB NB	Southwest	085-B(011)	2009	2	19	3	10	28	0	56	0	0	0		38	64		84.6	Good	NHS
ADOT	07220	85		133.86	Woods Road RCB	Southwest	085-B(011)	2009	2	19	3	10	32	0	38	0	0	0		42	70		100.0	Good	
ADOT	07245	85		134.62	RCB	Southwest	085-B(011)	2009	2	19	7	8	62	99	78	0	0	0		99	99		70.0	Good	NHS
ADOT	07198	85		134.67	RCB SB	Southwest	085-B(011)	2009	2	19	5	10	55	12	38	0	0	0		41	69		99.7	Good	NHS
ADOT	04455	85		134.68	RCB NB	Southwest	F-159(2)	1956	2	19	5	10	54	0	40	44	0	8	611	35	58		99.5	Good	NHS
ADOT	07199	85		135.37	RCB SB	Southwest	085-B(011)	2009	2	19	3	10	32	3	38	0	0	0		41	69		99.7	Good	NHS
ADOT	04456	85		135.38	RCB NB	Southwest	F-159(1)	1956	2	19	3	10	32	0	44	0	0	2		43	72		99.7	Fair	NHS
ADOT	04457	85		136.95	RCB EFR	Southwest	F-159(1)	1956	2	19	3	10	32	0	44	44.1	0	8	611	35	59		99.8	Good	NHS
ADOT	07200	85		136.99	RCB	Southwest	085-B(011)	2009	2	19	3	10	32	0	76	0	0	0		78	99		84.2	Good	NHS
ADOT	02524	85		138.38	Lewis Prison RD TI OP NB	Southwest	085-B(005)	2005	5	2	1	132	138	0	38	42	16.86		911	36	99		100.0	Good	NHS
ADOT	02680	85		138.38	Lewis Prison RD TI OP SB	Southwest	085-B(005)	2005	5	2	1	132	138	0	38	42	16.73		911	36	99		100.0	Good	NHS
ADOT	07074	85		138.56	RCB	Southwest	F023-1-526	1999	2	19	5	12	64	33	32	0	0	0		82	99		99.9	Fair	
ADOT	07111	85		138.64	RCB EFR	Southwest	NH-085-B(005)B	2006	2	19	3	10	32	7	54	0	0	0		42	70		100.0	Good	
ADOT	07110	85		138.66	RCB	Southwest	NH-085-B-(005)B	2006	2	19	3	10	32	10	90	0	0	0		42	70		84.2	Good	NHS
ADOT	07136	85		138.66	RCB WFR	Southwest	085-B(009)B	2008	2	19	3	10	32	20	38	0	0	0		83	99		99.9	Good	
ADOT	07137	85		139.9	RCB	Southwest	085-B(009)B	2008	2	19	5	10	55	10	81	0	0	0		99	99		70.0	Good	NHS
ADOT	00466	85		141.08	Rainbow Wash Bridge NB	Southwest	F-159(1)	1956	2	1	3	30	81	0	42	41.8	0	2	911	27	46		92.2	Good	NHS
ADOT	02771	85		141.1	Rainbow Wash Bridge SB	Southwest	085-B(009)B	2008	2	1	6	34	202	3	38	42	0	0	911	46	77		99.5	Good	NHS
ADOT	04458	85		141.61	RCB	Southwest	F-159(1)	1956	2	19	5	10	54	7	85	0	0	0		99	99		69.8	Good	NHS
ADOT	02279	85		147.75	Gila River Bridge SB	Southwest	AC-STP-023-1(19)	1995	6	2	28	129	3625	0	38	42	0		911	38	63		99.5	Fair	NHS
ADOT	02280	85		147.75	Gila River Bridge NB	Southwest	AC-STP-023-1(24)B	2000	6	2	28	129	3625	0	38	42	0		911	41	73		99.5	Good	NHS

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS	
ADOT	07172	85		150.51	BWCDD Canal RCB	Southwest	STP-085-B(13)A	2007	2	19	2	10	21	13	98	0	0	0	00	36	60		78.9	Good	NHS	
ADOT	01790	85		153.35	Roosevelt Canal Br NB FR	Southwest	F-023-1-505	1976	5	5	1	40	43	24	28	41.3	0	3	911	39	65		97.8	Good		
ADOT	01504	95		22.39	E Main Canal Br	Southwest	SU-264(10)	1969	5	2	1	72	76	0	64	64	0		211	36	82		95.7	Fair	NHS	
ADOT	00504	95		33.55	Gila Canal Br	Southwest	NS-264(57)A	1957	1	4	3	36	110	9	40	40	0	2	510	39	65		82.9	Fair		
ADOT	20035	95		34.46	Fortuna Wash Bridge	Southwest	095 YU 034	2016	2	1	15	43.5	602	15	84	84	0		911	56	93		84.9	Good	NHS	
ADOT	00343	95		38	Wellton Mohawk Canal Bridge	Southwest	FAS-264(50)B	1950	2	4	3	31	94	20	28	28	0	3	510	36	55	F	58.0	Fair		
ADOT	02408	95		38.83	Gila River Br	Southwest	ER-063-1(9)	1993	5	5	16	43	685	45	48	46.3	0	2	411	44	74		80.0	Fair		
ADOT	05006	95		42.5	RCB	Southwest	S-264(3)	1957	2	19	3	10	32	0	60	0	0	3	600	36	58		65.0	Fair	NHS	
ADOT	05007	95		46.8	RCB	Southwest	S-264(3)	1957	2	19	4	10	43	0	34	0	0		600	83	99		80.0	Fair	NHS	
ADOT	00583	95		53.28	Castle Dome Wash Br	Southwest	NS-264(61)A	1961	2	1	6	30	171	45	34	32.3	0	1	911	26	43		58.5	Fair	NHS	
ADOT	07109	95		55.92	RCB	Southwest	U-095-B-504	2003	2	19	4	10	49	30	40	0	0		000	42	70		82.8	Good	NHS	
ADOT	05008	95		73.98	RCB	Southwest	NFS-264(61)B	1963	2	19	3	10	32	0	40	0	0			42	70		65.0	Good	NHS	
ADOT	05009	95		75.7	RCB	Southwest	S-264(8)	1967	2	19	3	8	26	0	36	0	0			49	83		69.0	Fair	NHS	
ADOT	05010	95		76.74	RCB	Southwest	S-264(8)	1967	2	19	4	10	43	0	36	0	0			34	57		80.1	Fair	NHS	
ADOT	05011	95		77.27	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	36	0	0			42	70		69.0	Fair	NHS	
ADOT	05012	95		77.47	RCB	Southwest	S-264(8)	1967	2	19	2	10	21	0	35	0	0			84	99		80.9	Fair	NHS	
ADOT	05013	95		77.97	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0			42	70		80.9	Fair	NHS	
ADOT	05014	95		79.01	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0			42	70		69.0	Fair	NHS	
ADOT	05015	95		79.75	RCB	Southwest	S-264(8)	1967	2	19	5	10	54	0	35	0	0			85	99		69.0	Fair	NHS	
ADOT	05016	95		80.41	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0			42	70		69.0	Fair	NHS	
ADOT	05017	95		81.23	RCB	Southwest	S-264(9)	1968	2	19	2	10	21	0	35	0	0			42	71		80.9	Good	NHS	
ADOT	05018	95		81.57	RCB	Southwest	S-264(9)	1968	2	19	4	10	43	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05019	95		82.27	RCB	Southwest	S-264(9)	1968	2	19	6	10	64	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05020	95		82.67	RCB	Southwest	S-264(9)	1968	2	19	6	10	64	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05021	95		83.63	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05022	95		84.35	RCB	Southwest	S-264(9)	1968	2	19	2	10	21	0	35	0	0			42	71		80.9	Good	NHS	
ADOT	05023	95		84.86	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05024	95		85.24	RCB	Southwest	S-264(9)	1961	2	19	3	8	26	0	35	0	0			99	99		80.9	Good	NHS	
ADOT	05025	95		85.58	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0			42	70		80.9	Good	NHS	
ADOT	05026	95		86.44	RCB	Southwest	S-264(9)	1968	2	19	3	8	26	0	38	0	0			99	99		80.9	Good	NHS	
ADOT	05027	95		93.9	RCB	Southwest	NS-264(502)	1962	2	19	4	10	49	30	28	0	0			42	70		80.9	Good	NHS	
ADOT	07117	95		96.02	RCB	Southwest	U-095-B-503	2005	2	19	3	10	32	10	44	0	0			42	70		80.9	Good	NHS	
ADOT	05028	95		97.95	RCB	Southwest	NS-264(502)	1962	2	19	4	10	43	0	28	0	0	7	-00	36	58		77.9	Good	NHS	
ADOT	05029	95		99.88	RCB	Southwest	NS-264(61)B	1961	2	19	6	10	64	0	28	0	0			42	70		80.0	Good	NHS	
ADOT	05031	95		103.8	RCB	Southwest	S-264(512)	1969	2	19	6	10	75	30	34	0	0			42	70		99.2	Good	NHS	
ADOT	05030	95		104.1	RCB	Southwest	I-10-1(5)	1964	2	19	3	12	37	30	62	0	0			99	99		83.5	Good	NHS	
ADOT	02046	95		109.67	Plomosa Wash Bridge	Southwest	F-063-2-912	1987	2	1	3	30	83	15	68	68	0		400	45	76		80.0	Fair	NHS	
ADOT	07084	95		110.14	Scaddan Wash RCB	Southwest	NH-063-2(25)	2001	2	19	6	10	90	45	68	0	0	3	300	33	55		80.6	Good	NHS	
ADOT	07083	95		110.5	Plymouth Wash RCB	Southwest	063-2(25)B	2001	2	19	14	10	179	32	68	0	0	3	300	33	55		83.3	Good	NHS	
ADOT	06867	95		111.4	Dump Wash RCB	Southwest	F-063-2-509	1989	2	19	3	10	35	20	30	0	0			99	99		85.6	Good	NHS	
ADOT	01917	95		114.55	Climax Wash Bridge	Southwest	F-063-1-501	1984	2	1	8	25	194	0	38	38	0			911	74	99		89.7	Fair	NHS
ADOT	01321	95		131.33	Bouse Wash Bridge	Southwest	S-264(505)	1970	2	1	17	35	584	0	34	34	0			110	36	60		70.8	Fair	NHS
ADOT	01488	95	S	142.30	Colorado River Br	Southwest		2015	6	6	4	185.93	669	99	67	67	0	0	100	36	36	S	81.3	Poor		
ADOT	01522	95		147.16	Osborne Wash Bridge	Southwest	S-405-513	1971	2	1	8	35	269	0	80	80	0	3	911	32	54		82.9	Good	NHS	
ADOT	06819	95		148.33	Osborne Wash RCB	Southwest	B-063-2-506	1986	2	19	4	6	30	30	72	0	0			99	99		65.0	Good	NHS	
ADOT	02029	95		148.5	Rio Vista Rd UP	Southwest	B-063-2-506	1986	5	6	1	168	171	14	34	38	28.74			911	41	99		98.0	Fair	
ADOT	02403	95		154.9	Buckskin Ped UP	Southwest	N-900-559	1994	5	2	1	135	140	0	0	6	18.33			600	0	0		-2.0	Good	NHS
ADOT	06015	95		156.43	RCB	Southwest	NS-405(61)A	1961	2	19	2	10	29	45	36	0	0			86	99		84.9	Good	NHS	
ADOT	07239	95		156.71	Giers Wash RCB	Southwest	095-C(202)	2011	2	19	2	10	21	0	34	0	0	0		41	69		98.7	Good	NHS	
ADOT	06016	95		156.82	Giers Wash RCB	Southwest	NS-405(61)A	1961	2	19	3	10	32	0	35	0	0			41	69		84.9	Fair	NHS	
ADOT	01407	95		160.86	CAP Canal Intake Br	Southwest	USBR-344	1981	4	7	3	133	335	0	38	38	0			911	38	64		78.0	Good	NHS
ADOT	01272	95		161.62	Bill Williams Riv Br	Southwest	S-405(4)	1967	5	2	14	76	1126	0	33	32.4	0	1	911	43	90		82.8	Fair	NHS	
ADOT	02708	195		18.17	County 19th Street OP NB	Southwest	STP-900-A(055)	2009	1	1	1	47	49	0	40	42	19.18			911	75	99		99.7	Good	NHS
ADOT	02709	195		18.17	County 19th Street OP SB	Southwest	STP-900-A(055)	2009	1	1	1	47	49	0	40	42	19.02			911	75	99		99.8	Good	NHS
ADOT	02963	195		27.13	B Lateral Canal Br	Southwest	S-263(4)	1971	5	5	1	36	38	1	91	112	0	4	311	43	73		92.7	Good		
ADOT	02964	195		27.38	UPRR UP	Southwest	SG263(3)	1969	5	5	4	42	139	9	0	32	15.47	2	100	72	72		-2.0	Good		
CAWCD	00984	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	76	154	0	28	40	0			911	47	85		100.0	Good	
CAWCD	00985	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	82	165	0	28	40	0			911	50	95		100.0	Good	
CAWCD	00986	0	0	0	CAP Canal Bridge	Southwest	DC-7298	1980	5	2	1	85	87	0	28	28	0			911	37	75		98.0	Good	
CAWCD	00987	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1985	5	2	1	91	93	23	28	32	0	1	911	50	99		100.0	Good		

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 8/29/2018

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Invt Rtg	Opr Rtg	Def	SR	Bridge Condition	NHS
CAWCD	00988	0		0	CAP Canal Bridge	Southwest	3D-C7477	1985	5	2	1	101	103	32	32	32	0		911	48	99		100.0	Good	
CAWCD	00989	0		0	CAP Canal Bridge	Southwest	3D-C7477	1985	5	2	1	87	89	16	24	24	0		911	47	88		100.0	Good	
CAWCD	00990	0		0	CAP Canal Bridge	Southwest	DC-7195	1977	5	2	1	85	87	9	42	32	0		911	44	88		95.0	Good	
CAWCD	00992	0		0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	83	168	0	28	40	0		911	49	96		100.0	Good	
CAWCD	00993	0		0	CAP Canal Bridge	Southwest		1982	5	2	1	83	85	0	20	20	0		911	38	75		98.0	Good	
CAWCD	00994	0		0	CAP Canal Bridge	Southwest		1981	5	2	1	83	85	0	20	20	0		911	38	75		98.0	Good	
CAWCD	00995	0		0	CAP Canal Bridge	Southwest		1982	5	2	1	88	90	18	20	20	0		911	38	80		98.0	Good	
CAWCD	00996	0		0	CAP Canal Bridge	Southwest		1981	5	2	1	86	88	0	36	36	0		911	41	87		98.0	Good	
CAWCD	01487	0		0	CAP Canal Bridge	Southwest	DC-7394	1981	5	2	1	84	85	0	34	32	0	3	911	48	98		93.8	Good	
CAWCD	01844	0		0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	1	101	103	26	28	40	0		911	55	99		100.0	Good	