

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	RT MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	00486	8	B	.01	Colorado River Br	Southwest		1956	4	2	5	180	837	0	62	52	0		501		71.6	Good	NHS	
ADOT	01700	8		.01	Colorado River Viaduct EB	Southwest	I-8-9(2)	1978	6	5	15	214	2749	0	39	39	25	0	911	S	92.2	Poor	NHS	
ADOT	01701	8		.01	Colorado River Viaduct WB	Southwest	I-8-9(2)	1978	6	5	14	220	2668	0	39	39	25		411		94.2	Fair	NHS	
ADOT	00487	8	B	0.11	Yuma Canal Bridge	Southwest	NFA-407(56)A	1956	3	2	3	70	146	40	63	72	0		611		81.0	Fair	NHS	
ADOT	01322	8		0.58	4th St TI OP EB	Southwest	I-8-1(49)	1969	2	6	2	104	205	3	38	38	30.14		110		92.1	Fair	NHS	
ADOT	01323	8		0.58	4th St TI OP WB	Southwest	I-8-1(49)	1969	2	6	2	102	204	3	47	47	30.12		110		92.0	Fair	NHS	
ADOT	02075	8		0.58	4th Street UPRR UP	Southwest	IG-8-1(62)C	1976	5	5	4	52	167	14			15.33		100		-2.0	Fair	NHS	
ADOT	01380	8		2.23	US 95 TI UP	Southwest	I-8-1(49)	1970	2	6	2	132	260	28	108	108	16.33	1	911		96.0	Fair	NHS	
ADOT	01381	8		2.99	Ave 2E UP	Southwest	I-8-1(49)	1970	2	6	2	127	258	15	76	72	16.35		211		88.3	Fair	NHS	
ADOT	02681	8		3.99	Ave 3E TI OP EB	Southwest	IM-008-A-(014)B	2003	6	6	2	111	213	13	38	42	18.03		911		98.0	Good	NHS	
ADOT	02682	8		3.99	Ave 3E TI OP WB	Southwest	IM-008-A-(014)B	2003	6	6	2	111	213	13	38	42	18.1		911		98.0	Fair	NHS	
ADOT	01277	8		7.67	Araby Rd TI OP EB	Southwest	I-IG-8-1(42)	1968	2	4	4	52	147	8	38	38	15.23		411		92.0	Fair	NHS	
ADOT	01278	8		7.67	Araby Rd TI OP WB	Southwest	I-IG-8-1(42)	1968	2	4	4	52	147	8	38	38	15.29		411		92.0	Fair	NHS	
ADOT	01279	8		8.69	Fortuna SPRR OP EB	Southwest	I-IG-8-1(42)	1968	4	2	3	105	281	60	38	33	23.19		111		77.0	Fair	NHS	
ADOT	01280	8		8.7	Fortuna SPRR OP WB	Southwest	I-IG-8-1(42)	1968	4	2	3	105	281	60	38	33	22.88		111		77.0	Fair	NHS	
ADOT	01188	8		9.43	E Yuma TI OP EB	Southwest	I-IG-8-1(42)	1968	4	2	4	101	313	46	38	33	18.22		111		88.4	Fair	NHS	
ADOT	01281	8		9.44	E Yuma TI OP WB	Southwest	I-IG-8-1(42)	1968	4	2	4	101	313	46	38	33	17.69		111		88.4	Fair	NHS	
ADOT	02432	8		12.2	Fortuna Rd TI UP	Southwest	NH-8-1(95)	1997	6	2	2	131	268	0	80	80	16.63		911		99.0	Good	NHS	
ADOT	02117	8		14.25	Foothills Blvd TI UP	Southwest	IR-8-1(88)	1990	6	2	2	131	267	9	80	84	16.44		911		90.0	Good	NHS	
ADOT	01190	8		14.87	Fortuna Wash Br EB	Southwest	I-8-1(38)	1966	6	2	4	53	215	20	38	38	0	2	911		96.3	Fair	NHS	
ADOT	01191	8		14.87	Fortuna Wash Br WB	Southwest	I-8-1(38)	1967	6	2	4	53	215	20	38	38	0	2	911		96.4	Fair	NHS	
ADOT	01192	8		14.98	Frontage Rd OP EB	Southwest	I-8-1(38)	1966	2	1	3	35	94	0	38	38	15.53	2	911		94.3	Fair	NHS	
ADOT	01193	8		14.98	Frontage Rd OP WB	Southwest	I-8-1(38)	1966	2	1	3	35	94	0	38	38	15.81	2	911		94.4	Good	NHS	
ADOT	05228	8		16.41	RCB WB	Southwest	I-8-1(38)	1967	2	19	4	10	49	30	38	0	0	0	-00		97.4	Good	NHS	
ADOT	07082	8		16.41	Dry Wash RCB EB	Southwest	BR-8-A(2)	2002	2	19	4	10	43	0	38	0	0	0	00		97.3	Good	NHS	
ADOT	05229	8		16.79	RCB WB	Southwest	I-8-1(38)	1967	2	19	3	10	45	45	38	0	0	0	-00		97.4	Good	NHS	
ADOT	01566	8		16.85	Dublin Wash Br EB	Southwest	NRH-8(8)B	1927	2	1	2	20	40	45	38	40	0	7	911		86.4	Fair	NHS	
ADOT	06743	8		16.85	Insp Sta Ramp RCB EB	Southwest	I-8-1(77)	1982	2	19	2	12	38	49	34	0	0	0	-00		97.3	Good	NHS	
ADOT	05230	8		17.76	RCB EB	Southwest	I-8-1(21)	1967	2	19	3	10	32	0	38	0	0	0	-00		97.3	Good	NHS	
ADOT	05231	8		17.77	RCB WB	Southwest	I-8-1(21)	1967	2	19	3	10	32	0	38	0	0	0	-00		97.4	Good	NHS	
ADOT	00303	8		18.12	Wash Br EB	Southwest	FAP-82B	1927	2	1	2	13	28	3	38	63.7	0	6	610		85.4	Good	NHS	
ADOT	06714	8		18.5	RCB EB	Southwest	FAP-82B	1929	2	19	2	10	30	45	38	0	0	0	0	00		94.7	Good	NHS
ADOT	00971	8		18.8	Telpas OP WB Over EB	Southwest	I-8-1(21)	1967	4	2	3	159	267	0	38	42.1	19.52		911		88.9	Fair	NHS	
ADOT	00972	8		20.4	Telpas OP WB Over EB	Southwest	I-8-1(21)	1967	4	2	3	103	249	51	38	42.1	16.4		911		76.9	Fair	NHS	
ADOT	01324	8		21.04	Dome Vly Rd TI UP EB	Southwest	I-8-1(35)	1969	2	4	3	70	183	29	34	34	19.38	0	411		98.1	Fair	NHS	
ADOT	01325	8		21.06	Dome Vly Rd TI UP WB	Southwest	I-8-1(35)	1969	2	4	3	68	155	17	34	34	16.14	0	411		95.4	Fair	NHS	
ADOT	05232	8		21.63	RCB	Southwest	I-8-1(35)	1969	2	19	2	12	25	0	150	0	0	0	-00		65.0	Good	NHS	
ADOT	01327	8		22.9	Red Top Wash Br WB	Southwest	I-8-1(35)	1967	6	2	2	76	157	20	38	38	0	0	411		96.5	Fair	NHS	
ADOT	01326	8		22.91	Red Top Wash Br EB	Southwest	I-8-1(35)	1967	6	2	2	76	157	20	38	38	0	0	411		96.4	Fair	NHS	
ADOT	01328	8		24.1	Liguria Wash Br EB	Southwest	I-8-1(35)	1967	6	2	6	78	469	30	38	38	0	0	411		96.4	Fair	NHS	
ADOT	01329	8		24.1	Liguria Wash Br WB	Southwest	I-8-1(35)	1967	6	2	6	78	469	30	38	38	0	0	411		96.5	Fair	NHS	
ADOT	05233	8		26.53	RCB	Southwest	I-8-1(32)	1969	2	19	3	10	32	0	76	0	0	0	-00		81.8	Good	NHS	
ADOT	01330	8		26.7	Ave 25E OP EB	Southwest	I-8-1(32)	1965	2	1	3	40	107	11	38	38	18.42		411		93.8	Fair	NHS	
ADOT	01331	8		26.7	Ave 25E OP WB	Southwest	I-8-1(32)	1965	2	1	3	40	107	11	38	38	19.27	1	411		94.3	Fair	NHS	
ADOT	05234	8		29.74	RCB	Southwest	I-8-1(32)	1969	2	19	2	10	21	0	76	0	0	0	-00		65.0	Good	NHS	
ADOT	01332	8		30.8	Wellton TI UP	Southwest	I-8-1(32)	1965	2	4	4	81	254	15	40	40	16.2		111		95.8	Fair	NHS	
ADOT	01333	8		31.5	Wellton Canal Br EB	Southwest	I-8-1(32)	1967	2	6	3	51	109	0	38	38	0	0	411		96.6	Fair	NHS	
ADOT	01334	8		31.5	Wellton Canal Br WB	Southwest	I-8-1(32)	1967	2	6	3	51	109	0	38	38	0	0	411		96.5	Fair	NHS	
ADOT	05236	8		32.37	RCB	Southwest	I-8-1(29)	1969	2	19	3	10	32	0	76	0	0	0	-00		81.9	Good	NHS	
ADOT	01335	8		32.89	Ave 31E UP	Southwest	I-8-1(29)	1965	2	6	4	85	262	16	26	26	16.28		111		98.0	Fair	NHS	
ADOT	05237	8		33.91	RCB	Southwest	I-8-1(29)	1969	2	19	3	10	32	0	76	0	0	0	000		81.9	Good	NHS	
ADOT	01336	8		34.91	Ave 33E UP	Southwest	I-8-1(29)	1964	5	2	9	78	613	5	28	28	20.33		311		96.9	Good	NHS	
ADOT	02738	8		36.4	Mohawk Canal Br OP EB	Southwest	-800-A(003)A	2003	5	6	1	151	252	50	38	42	0	0	911		97.6	Fair	NHS	
ADOT	02739	8		36.4	Mohawk Canal Br OP WB	Southwest	-800-A(003)A	2003	5	6	1	151	253	55	38	42	0	0	911		96.6	Fair	NHS	
ADOT	01194	8		37.98	Antelope Hill TI UP	Southwest	I-8-1(26)	1967	4	2	4	81	258	14	32	30	16.25		911		90.7	Fair	NHS	
ADOT	05239	8		40.71	RCB	Southwest	I-8-1(26)	1966	2	19	2	10	21	0	76	0	0	0	-00		74.4	Good	NHS	
ADOT	01195	8		42.08	Tacna TI UP	Southwest	I-8-1(26)	1967	4	2	4	79	254	10	32	33	16.45		911		95.8	Fair	NHS	
ADOT	05241	8		42.62	RCB	Southwest	I-8-1(26)	1966	2	19	2	10	21	0	76	0	0	0	-00		78.3	Good	NHS	
ADOT	05243	8		44.61	RCB	Southwest	I-8-1(25)	1965	2	19	4	10												

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	05258	8		59.97	San Cristobal RCB WB	Southwest	I-8-1(13)	1962	2	19	6	10	65	0	38	0	0					97.2	Good	NHS
ADOT	00681	8		67.43	Dateland TI OP EB	Southwest	I-8-1(10)	1962	2	1	3	40	108	24	38	38	14.24	2	911		95.0	Fair	NHS	
ADOT	00682	8		67.43	Dateland TI OP WB	Southwest	I-8-1(10)	1962	2	1	3	40	108	24	38	38	14.21	2	911		95.0	Fair	NHS	
ADOT	05259	8		72.18	RCB	Southwest	IN-2-1(1)	1956	2	19	5	10	54	0	76	0	0					69.9	Good	NHS
ADOT	00683	8		73.48	Aztec TI OP EB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	14.46	1	911		96.0	Fair	NHS	
ADOT	00684	8		73.48	Aztec TI OP WB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	14.48	1	911		96.0	Fair	NHS	
ADOT	05261	8		75.12	Canyon Diablo RCB	Southwest	IN-002-1(2)	1956	2	19	6	10	75	30	38	0	0					69.9	Fair	NHS
ADOT	00685	8		78.4	Spot Rd TI OP EB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	13.88	1	911		94.0	Fair	NHS	
ADOT	00686	8		78.4	Spot Rd TI OP WB	Southwest	I-8-1(8)	1962	2	1	3	36	97	0	38	39.8	13.87	1	911		94.0	Fair	NHS	
ADOT	05263	8		83.01	RCB WB	Southwest	I-8-2(23)	1962	2	19	5	12	111	55	38	0	0		600			97.7	Fair	NHS
ADOT	00317	8		83.14	Wash Bridge EB	Southwest	FA-69-1 REO	1930	2	1	5	23	116	52	38	40	0	3	911		94.7	Fair	NHS	
ADOT	00687	8		87.04	Sentinel TI OP EB	Southwest	I-8-2(23)	1962	2	1	3	36	97	0	38	38	14.91	2	810		95.0	Fair	NHS	
ADOT	00688	8		87.04	Sentinel TI OP WB	Southwest	I-8-2(23)	1962	2	1	3	36	97	0	38	38	15.37	2	810		95.0	Fair	NHS	
ADOT	05264	8		87.25	RCB & Ramps & NFR	Southwest	FI-69(3)	1949	2	19	2	10	21	0	90	0	0					81.5	Good	NHS
ADOT	05265	8		90.86	RCB	Southwest	FI-69(4)	1953	2	19	3	10	37	30	76	0	0					70.0	Good	NHS
ADOT	05267	8		94.29	RCB	Southwest	FI-69(4)	1953	2	19	3	10	32	0	76	0	0					70.0	Good	NHS
ADOT	05269	8		97.42	RCB	Southwest	FI-69(5)	1953	2	19	3	10	32	0	76	0	0					70.0	Good	NHS
ADOT	00509	8		102.27	Painted Rock TI OP EB	Southwest	I-002-2(6)	1958	2	1	3	33	90	0	38	38	15.21	1	911		93.0	Fair	NHS	
ADOT	00510	8		102.27	Painted Rock TI OP WB	Southwest	I-002-2(6)	1958	2	1	3	33	90	0	38	38	15.36	1	911		93.0	Good	NHS	
ADOT	00566	8		106.54	Paloma Rd TI OP EB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38	14.23	2	911		95.0	Fair	NHS	
ADOT	00567	8		106.54	Paloma Rd TI OP WB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38	14.33	3	911		95.0	Fair	NHS	
ADOT	00489	8		107.02	Gillespie Canal Br EB	Southwest	I(52)-I-002-2(1)	1957	2	1	2	21	43	30	38	40	0	2	911		59.0	Poor	NHS	
ADOT	01009	8		107.02	Gillespie Cnl Br SFR	Southwest	FAP-56	1923	2	1	2	22	45	20	40	45	0	2	400			73.7	Fair	
ADOT	00568	8		107.07	Gillespie Cnal Br WB	Southwest	I-8-2(18)	1960	2	1	2	21	43	35	38	38	0	3	911		85.6	Fair	NHS	
ADOT	00490	8		109.55	Gillespie Canal Br EB	Southwest	I(52)-IN002-2(1)	1957	2	1	2	25	51	0	38	40	0	3	911		78.0	Fair	NHS	
ADOT	00569	8		109.55	Gillespie Cnal Br WB	Southwest	I-8-2(18)	1960	2	1	2	25	51	5	38	38	0	2	911		96.7	Fair	NHS	
ADOT	01010	8		109.55	Gillespie Cnl Br SFR	Southwest	FAP-56(3)	1923	2	1	2	27	53	3	20	45	0	2	400			65.8	Fair	
ADOT	01505	8		110.35	Wash Bridge SFR	Southwest	FA-56 2ndRec	1923	1	1	2	22	44	0	22	44	0	4	400			71.6	Fair	
ADOT	05271	8		110.35	RCB	Southwest	IN-002-2(1)	1957	2	19	4	10	43	15	76	0	0	2	911			77.1	Fair	NHS
ADOT	00570	8		111.42	Citrus Vly TI OP EB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38.7	14.73	1	911		96.0	Fair	NHS	
ADOT	00571	8		111.42	Citrus Vly TI OP WB	Southwest	I-8-2(18)	1960	2	1	3	36	97	0	38	38.7	14.68	1	911		96.0	Fair	NHS	
ADOT	05273	8		112.01	RCB & SFR	Southwest	IN-002-2(1)	1938	2	19	2	10	21	3	76	0	0					74.8	Fair	NHS
ADOT	00439	8		113.27	Sauceda Wash Br SFR	Southwest	FA-56(2R)	1930	2	1	4	22	89	0	24	24	0	3	111			78.1	Fair	
ADOT	00442	8		113.27	Sauceda Wash Br EB	Southwest	FI-56-3	1955	2	1	4	25	90	0	38	40	0	2	110			85.6	Fair	NHS
ADOT	01554	8		113.27	Sauceda Wash Br WB	Southwest	I(52)-8-2(40)	1971	2	1	4	30	111	30	38	38	0	0	110			95.6	Fair	NHS
ADOT	06201	8		113.9	RCB & SFR	Southwest	I(52)-8-2(40)	1971	2	19	3	12	44	30	76	0	0					81.8	Good	NHS
ADOT	06202	8		114.29	RCB & SFR & NFR	Southwest	I(52)-8-2(40)	1971	2	19	3	12	39	12	76	0	0					82.2	Good	NHS
ADOT	01555	8		115.14	SB 8 & SPRR OP EB	Southwest	I(52)-8-2(40)	1971	4	2	7	102	659	60	38	38	23.8		100			93.6	Fair	NHS
ADOT	01556	8		115.14	SB 8 & SPRR OP WB	Southwest	I(52)-8-2(40)	1971	4	2	7	102	659	60	38	38	23.62		100			94.7	Fair	NHS
ADOT	06203	8		115.58	RCB	Southwest	I(52)-8-2(40)	1971	2	19	3	10	37	30	76	0	0					82.4	Good	NHS
ADOT	01557	8		115.62	Hwy 85 OP WB	Southwest	I(52)-8-2(40)	1971	2	6	3	86	171	30	38	38	15.11		110			96.8	Fair	NHS
ADOT	01558	8		115.62	Hwy 85 OP EB	Southwest	I(52)-8-2(40)	1971	2	6	3	86	171	30	38	38	23		110			96.8	Fair	NHS
ADOT	01394	8		115.95	Gila Bend Cnl Br EB	Southwest	I(52)-8-2(44)	1965	5	2	1	85	90	34	47	47.9	0	400				97.8	Fair	NHS
ADOT	01395	8		115.95	Gila Bend Cnl Br WB	Southwest	I(52)-8-2(44)	1965	5	2	1	85	90	34	38	38	0	400				96.8	Fair	NHS
ADOT	01339	8		116.35	TC & GBRR OP EB	Southwest	I(52)-8-2(44)	1965	6	2	3	39	120	7	38	38	23.82		400			96.8	Fair	NHS
ADOT	01340	8		116.35	TC & GBRR OP WB	Southwest	I(52)-8-2(44)	1965	6	2	3	39	120	7	38	38	23.65		400			96.8	Fair	NHS
ADOT	01341	8		116.76	County Rd OP EB	Southwest	I(52)-8-2(44)	1965	2	1	3	40	107	17	38	38	15.43		400			94.8	Fair	NHS
ADOT	01342	8		116.76	County Rd OP WB	Southwest	I(52)-8-2(44)	1965	2	1	3	40	107	17	38	38	15.58		400			94.8	Fair	NHS
ADOT	06493	8		116.87	RCB	Southwest	I(52)-8-2(44)	1970	2	19	2	10	29	45	76	0	0					82.4	Good	NHS
ADOT	06494	8		117.29	RCB	Southwest	I(52)-8-2(44)	1970	2	19	5	10	54	0	76	0	0					82.4	Good	NHS
ADOT	01343	8		117.43	Sand Tanks Wash Br EB	Southwest	I(52)-8-2(44)	1965	2	1	7	30	201	45	38	38	0	110				96.8	Fair	NHS
ADOT	01344	8		117.43	Sand Tanks Wash Br WB	Southwest	I(52)-8-2(44)	1965	2	1	7	30	201	45	38	38	0	110				96.8	Fair	NHS
ADOT	06495	8		117.5	RCB	Southwest	I(52)-8-2(44)	1970	2	19	3	10	32	0	76.001	0	0	4	600			81.2	Good	NHS
ADOT	06496	8		117.8	RCB	Southwest	I(52)-8-2(44)	1970	2	19	5	10	62	30	76	0	0					82.4	Good	NHS
ADOT	06497	8		117.84	RCB	Southwest	I(52)-8-2(44)	1970	2	19	4	12	59	30	76	0	0	2				82.4	Good	NHS
ADOT	06498	8		117.95	RCB	Southwest	I(52)-8-2(44)	1970	2	19	6	10	91	45	76	0	0					82.4	Good	NHS
ADOT	06499	8		118.1	RCB	Southwest	I(52)-8-2(44)	1970	2	19	3	10	37	30	76	0	0					82.4	Good	NHS
ADOT	00443	8	B	118.15	Wash Bridge	Southwest	FI-56(3)	1955	2	1</														

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	05283	8		137.1	RCB	Southwest	I-002-2(12)	1958	2	19	3	10	32	0	76	0	0	0				82.3	Good	NHS
ADOT	05285	8		137.5	RCB	Southwest	I-8-2(12)	1958	2	19	3	10	32	0	76	0	0	0		-00		69.3	Good	NHS
ADOT	05287	8		137.84	RCB	Southwest	I-8-2(12)	1958	2	19	4	10	43	0	76	0	0	0				68.7	Good	NHS
ADOT	05289	8		138.2	RCB	Southwest	I-8-2(12)	1958	2	19	2	10	21	0	76	0	0	0				69.3	Good	NHS
ADOT	05291	8		139.26	RCB	Southwest	I-8-2(4)	1958	2	19	4	10	43	0	76	0	0	0				69.3	Good	NHS
ADOT	00533	8		140.8	Freeman TI OP EB	Southwest	I-002-2(4)	1958	1	7	1	26	29	0	38	38	14.62	8	610			90.0	Good	NHS
ADOT	00534	8		140.8	Freeman TI OP WB	Southwest	I-002-2(4)	1958	1	7	1	26	29	0	38	38	14.22	8	610			90.0	Good	NHS
ADOT	05293	8		141.72	RCB EB	Southwest	I-8-2(4)	1959	2	19	6	10	74	30	38	38.4	0	6	611			97.8	Good	NHS
ADOT	05294	8		141.72	RCB WB	Southwest	I-8-2(4)	1959	2	19	6	10	74	30	38	38.4	0	6	611			97.8	Good	NHS
ADOT	05295	8		141.85	RCB	Southwest	I-8-2(4)	1959	2	19	3	10	32	0	76	0	0	0				69.3	Good	NHS
ADOT	05297	8		142.53	RCB EB	Southwest	I-8-2(4)	1959	2	19	6	10	65	0	38	38.2	0	6	611			97.6	Good	NHS
ADOT	05298	8		142.53	RCB WB	Southwest	I-8-2(4)	1959	2	19	6	10	65	0	38	38.2	0	6	611			97.6	Good	NHS
ADOT	05299	8		143.69	RCB	Southwest	I-8-2(11)	1959	2	19	2	10	21	0	76	0	0	0				69.3	Good	NHS
ADOT	05301	8		144.31	RCB EB	Southwest	I-8-2(11)	1959	2	19	8	10	100	30	38	38.3	0	4	611			96.5	Good	NHS
ADOT	05302	8		144.31	RCB WB	Southwest	I-8-2(11)	1959	2	19	8	10	100	30	38	40.1	0	6	611			96.5	Good	NHS
ADOT	00550	8		144.55	Vekol Road TI UP	Southwest	I-002-2(11)	1959	4	2	4	85	240	0	26	26	16.17		600			76.5	Fair	NHS
ADOT	00422	8		144.74	Vekol Wash Bridge WB	Southwest	NFA-152(54)B	1954	4	2	3	71	188	0	40	40	0	2	911			96.5	Fair	NHS
ADOT	00552	8		144.74	Vekol Wash Bridge EB	Southwest	I-002-2(11)	1959	4	2	3	71	190	0	48	48.1	0	1	911			97.8	Fair	NHS
ADOT	05303	8		145.91	RCB	Southwest	I-8-2(11)	1959	2	19	2	10	24	30	76	0	0	0				69.3	Good	NHS
ADOT	05305	8		146.74	RCB EB	Southwest	I-8-2(11)	1959	2	19	6	10	74	30	38	0	0	0				97.8	Good	NHS
ADOT	05306	8		146.74	RCB WB	Southwest	I-8-2(11)	1959	2	19	6	10	74	30	38	0	0	0				97.7	Good	NHS
ADOT	00619	10		.01	Ehrenberg Bridge	Southwest	I-002-2(11)	1960	3	2	5	246	1113	15	47	94	16.995		911			81.5	Good	NHS
ADOT	01704	10		.62	Poston Rd TI UP	Southwest	I-10-1(21)	1977	4	2	2	99	198	0	44	44	16.45		911			94.9	Fair	NHS
ADOT	05358	10		1.29	RCB	Southwest	FL-1(3)	1949	2	19	3	10	32	0	76	0	0	0				68.3	Good	NHS
ADOT	05359	10		1.77	Cinnabar Wash RCB EB	Southwest	FL-1(3)	1949	2	19	8	10	86	0	38	38	0	6				96.0	Good	NHS
ADOT	05360	10		1.77	Cinnabar Wash RCB WB	Southwest	I-10-1(8)	1963	2	19	8	10	86	0	38	0	0	0				97.0	Fair	NHS
ADOT	05361	10		2.83	RCB	Southwest	FL-1(3)	1949	2	19	4	10	43	0	76	0	0	0				68.3	Fair	NHS
ADOT	05363	10		4.13	RCB EB	Southwest	FL-1(3)	1949	2	19	9	10	98	0	38	0	0	0				97.0	Good	NHS
ADOT	05364	10		4.13	RCB WB	Southwest	I-10-1(8)	1963	2	19	9	10	112	30	38	0	0	0				97.0	Good	NHS
ADOT	00767	10		5.84	Tom Wells Rd TI UP	Southwest	I-10-11(18)2	1963	4	2	4	77	247	0	28	28	16.08		311			83.5	Fair	NHS
ADOT	05365	10		6.96	La Paz Arroyo RCB EW	Southwest	FL-1(3)	1949	2	19	4	12	59	30	76	0	0	0				68.3	Good	NHS
ADOT	05367	10		8.16	Gonzales Wash RCB WB	Southwest	FL-98(16)	1950	2	19	5	12	74	30	38	38.1	0	2	611			97.2	Good	NHS
ADOT	05368	10		8.49	Gonzales Wash RCB EB	Southwest	I-10-1(20)	1950	2	19	2	10	21	0	76	0	0	0		611		96.5	Good	NHS
ADOT	05369	10		8.6	Gonzales Wash RCB EB	Southwest	I-10-1(20)	1950	2	19	2	10	21	0	76	0	0	0				97.1	Good	NHS
ADOT	05370	10		8.83	Gonzales Wash RCB WB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	38	0	0	0				97.2	Good	NHS
ADOT	05371	10		9.33	Gonzales Wash RCB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	76	0	0	0				68.3	Good	NHS
ADOT	05373	10		9.52	Gonzales Wash RCB	Southwest	I-10-1(20)	1950	2	19	4	12	72	45	76	0	0	0				68.3	Good	NHS
ADOT	05375	10		9.83	Gonzales Wash RCB EW	Southwest	I-10-1(20)	1950	2	19	4	12	59	30	76	0	0	0				68.3	Good	NHS
ADOT	05378	10		9.99	RCB	Southwest	I-10-1(20)	1963	2	19	2	10	21	0	76	0	0	0				68.3	Good	NHS
ADOT	05379	10		10.17	Gonzales Wash RCB	Southwest	FL-1(4)	1950	2	19	4	12	72	45	76	0	0	0				68.3	Fair	NHS
ADOT	05381	10		10.29	Gonzales Wash RCB EW	Southwest	FL-98(16)	1950	2	19	3	12	54	45	76	0	0	0				68.3	Fair	NHS
ADOT	05383	10		11.11	RCB	Southwest	FL-98(16)	1932	2	19	2	10	21	0	76	0	0	0				72.4	Good	NHS
ADOT	00755	10		11.95	Dome Rock TI OP EB	Southwest	I-10-1(15)	1963	2	1	3	33	90	0	38	38	14.14	3	911			95.0	Good	NHS
ADOT	00756	10		11.95	Dome Rock TI OP WB	Southwest	I-10-1(15)	1963	2	1	3	33	90	0	38	38	14.82	3	911			95.0	Good	NHS
ADOT	05385	10		12.64	RCB	Southwest	FL-98(16)	1953	2	19	2	10	21	99	76	0	0	0				73.7	Good	NHS
ADOT	05387	10		13.96	RCB	Southwest	FL-98(16)	1963	2	19	3	8	27	0	76	0	0	0				73.7	Good	NHS
ADOT	05389	10		15.16	RCB	Southwest	FL-98(20)	1953	2	19	3	10	32	99	76	0	0	0				73.7	Good	NHS
ADOT	05391	10		16.24	La Cholla Wash RCB E	Southwest	FL-98(20)	1953	2	19	9	10	98	0	38	39.2	0	2	911			95.4	Fair	NHS
ADOT	05392	10		16.24	La Cholla Wash RCB W	Southwest	I-10-1(15)	1963	2	19	9	10	97	0	38	0	0	0				97.4	Good	NHS
ADOT	00826	10		17.5	West Quartzsite TI UP	Southwest	I-10-1(5)	1964	4	2	4	78	249	0	28	28	15.92		311			78.4	Fair	NHS
ADOT	05393	10		17.78	RCB & SFR	Southwest	I-10-1(5)	1964	2	19	3	10	37	30	76	0	0	0				73.0	Good	NHS
ADOT	05218	10	B	17.92	RCB	Southwest	FA-98(6)	1933	2	19	2	10	21	12	68	0	0	5	600			78.3	Good	NHS
ADOT	00813	10		18.09	Quartzsite Ped OP	Southwest	I-10-1(5)	1964	4	2	2	78	299	0			16.68		6			-2.0	Fair	NHS
ADOT	05395	10		18.2	RCB & SFR	Southwest	I-10-1(5)	1964	2	19	3	10	32	0	76	102	0	3				94.5	Good	NHS
ADOT	05397	10		18.48	RCB	Southwest	I-10-1(5)	1964	2	19	6	10	64	0	76	0	0	0				73.0	Good	NHS
ADOT	00791	10		18.61	Tyson Wash Bridge EB	Southwest	I-10-1(5)	1964	2	1	14	30	410	0	38	42	0	4	911			97.2	Fair	NHS
ADOT	00792	10		18.61	Tyson Wash Bridge WB	Southwest	I-10-1(5)	1964	2	1	14	30	410	0	38	42	0	4	911			97.2	Fair	NHS
ADOT	05399	10		18.72	RCB	Southwest	I-10-1(5)	1964	2	19	3	10	37	30	76	0	0	0				73.0	Good	NHS
ADOT	01451	10		18.89	SR 95 UP	Southwest	AC-NH 063-2(22)P	2001	5	2	2	132	368	10	68	68	17.35		311			85.0	Fair	NHS
ADOT	07222	10	B	19.55	Piomaso Wash RCB	Southwest	IM-10-1-(88)	2005	2	19	4	10	43	10	68	0	0	0				80.5	Good	NHS
ADOT	05401	10		19.56	RCB	Southwest	I-10-1(5)	1964	2	19	4	10	43	0	100	0	0	0				73.0	Good	NHS
ADOT	07070	10	B	19.76	Piomaso Wash RCB	Southwest	IM-10-1-(88)	2005	2	19	4	10	43	0	68	0	0	0				80.5	Good	NHS
ADOT	02726	10		19.9	Riggles Avenue TI UP	Southwest	IM-10-1(88)	2002	5	2	2	130	263	8	68	68	17.37		311			98.5	Good	NHS
ADOT	05403	10		19.93	RCB	Southwest	I-10-1(5)	1964	2	19	4	10	49	30	140	0	0	0				73.0	Good	NHS
ADOT	05405	10		20.83	RCB	Southwest	I-10-1(11)	1960	2	19	4	10	60	45	76	0	0	0				70.0	Good	NHS
ADOT	05407	10		22.06	RCB	Southwest	I-10-1(11)	1960	2	19	6	10	91	45	76	0	0	0				70.0	Good	NHS
ADOT	00769	10		26.65	Gold Nugget TI UP	Southwest	I-10-1(19)	1963	4	2	4	78	250	0										

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS
ADOT	01201	10		31.17	Brenda TI UP	Southwest	I-10-1(24)	1967	2	6	3	138	377	25	40	30	17.71		111		82.0	Fair	
ADOT	06200	10		31.5	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	24	30	38	0	0				82.0	Good	NHS
ADOT	06238	10		31.5	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	24	30	38	0	0				97.2	Good	NHS
ADOT	06239	10		31.55	RCB EB	Southwest	I-10-1(24)	1969	2	19	6	10	93	45	38	0	0				97.2	Good	NHS
ADOT	06240	10		31.56	RCB WB	Southwest	I-10-1(24)	1969	2	19	5	10	64	30	38	0	0			00	97.1	Good	NHS
ADOT	06241	10		32.5	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	12	25	30	38	0	0				97.2	Good	NHS
ADOT	06242	10		32.51	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	12	25	30	38	0	0				97.1	Fair	NHS
ADOT	06243	10		32.55	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0				97.2	Good	NHS
ADOT	06244	10		32.55	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0				97.1	Good	NHS
ADOT	01202	10		33.78	Ramsey Mine Rd UP	Southwest	I-10-1(24)	1967	2	6	3	125	330	0	26	26	16.2		111		90.9	Fair	
ADOT	06245	10		33.95	RCB EB	Southwest	I-10-1(24)	1969	2	19	3	12	38	30	38	0	0				96.9	Good	NHS
ADOT	06246	10		33.95	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	12	38	30	38	0	0				96.9	Good	NHS
ADOT	06247	10		34.1	RCB EB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0				96.9	Good	NHS
ADOT	06248	10		34.1	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0				96.9	Good	NHS
ADOT	06249	10		34.15	RCB EB	Southwest	I-10-1(24)	1969	2	19	4	10	44	0	38	0	0				96.9	Good	NHS
ADOT	06250	10		34.15	RCB WB	Southwest	I-10-1(24)	1969	2	19	3	10	33	0	38	0	0				96.9	Good	NHS
ADOT	06251	10		34.25	RCB EB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0				96.9	Good	NHS
ADOT	06252	10		34.25	RCB WB	Southwest	I-10-1(24)	1969	2	19	2	10	21	0	38	0	0				96.9	Good	NHS
ADOT	06253	10		35.15	RCB EB	Southwest	I-10-1(24)	1967	2	19	6	10	64	0	38	0	0				96.9	Good	NHS
ADOT	06254	10		35.15	RCB WB	Southwest	I-10-1(24)	1969	2	19	6	10	64	0	38	0	0				96.9	Good	NHS
ADOT	06255	10		35.17	RCB WB	Southwest	I-10-1(35)	1974	2	19	3	11	34	20	38	0	0				96.9	Good	NHS
ADOT	06256	10		35.18	RCB EB	Southwest	I-10-1(24)	1967	2	19	3	11	32	20	38	0	0				96.9	Good	NHS
ADOT	01203	10		37.11	Wash Bridge EB	Southwest	I-10-1(24)	1967	2	1	5	35	164	45	38	38	0	1	911		95.9	Fair	NHS
ADOT	01204	10		37.11	Wash Bridge WB	Southwest	I-10-1(24)	1967	2	1	5	35	164	45	38	38	0	1	111		83.7	Fair	NHS
ADOT	01205	10		39.37	New Water Mtn Br EB	Southwest	I-10-1(27)	1967	2	1	4	30	111	45	38	38	0	1	911		95.9	Fair	NHS
ADOT	01206	10		39.37	New Water Mtn Br WB	Southwest	I-10-1(27)	1967	2	1	4	30	111	45	38	38	0	2	911		84.0	Fair	NHS
ADOT	06257	10		39.9	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	14	29	45	38	0	0				96.9	Good	NHS
ADOT	06258	10		39.91	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	14	29	45	38	0	0				96.9	Good	NHS
ADOT	06259	10		40.24	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	12	24	30	38	0	0				96.9	Good	NHS
ADOT	06260	10		40.25	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	12	24	30	38	0	0				96.9	Good	NHS
ADOT	06261	10		42.8	RCB EB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0				96.9	Good	NHS
ADOT	06262	10		42.8	RCB WB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0				96.9	Fair	NHS
ADOT	06263	10		42.95	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06264	10		42.95	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06265	10		43.05	RCB EB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0				96.9	Good	NHS
ADOT	06266	10		43.05	RCB WB	Southwest	I-10-1(27)	1967	2	19	4	8	35	0	38	0	0				96.9	Good	NHS
ADOT	06267	10		43.4	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	10	32	0	38	0	0				96.9	Good	NHS
ADOT	06268	10		43.4	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	10	32	0	38	0	0				96.9	Good	NHS
ADOT	06269	10		43.65	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06270	10		43.65	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06271	10		43.95	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06272	10		43.95	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Good	NHS
ADOT	06273	10		44.2	RCB EB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Fair	NHS
ADOT	06274	10		44.2	RCB WB	Southwest	I-10-1(27)	1967	2	19	3	8	26	0	38	0	0				96.9	Fair	NHS
ADOT	01207	10		45.34	Vicksburg Rd TI UP	Southwest	I-10-1(27)	1967	2	6	3	127	332	10	34	32.4	15.9		911		91.8	Fair	
ADOT	06275	10		48.2	RCB EB	Southwest	I-10-1(27)	1967	2	19	2	10	21	0	38	0	0				97.0	Good	NHS
ADOT	06276	10		48.2	RCB WB	Southwest	I-10-1(27)	1967	2	19	2	10	21	0	38	0	0				97.1	Fair	NHS
ADOT	06277	10		51.75	RCB EB	Southwest	I-10-1(30)	1970	2	19	3	10	32	0	38	0	0				97.0	Good	NHS
ADOT	06278	10		51.75	RCB WB	Southwest	I-10-1(30)	1970	2	19	3	10	32	0	38	0	0				97.1	Good	NHS
ADOT	01410	10		52.24	CAP Canal Br WB	Southwest	I-10-1(30)	1982	5	2	2	73	152	17	66	65.1	0	1	911		97.0	Good	NHS
ADOT	01409	10		52.25	CAP Canal Br EB	Southwest	I-10-1(30)	1982	5	2	2	65	137	17	77	77.4	0	1	911		97.0	Fair	NHS
ADOT	01384	10		53.94	Hovatter Rd TI UP	Southwest	I-10-1(30)	1970	2	6	3	125	352	0	40	40	16.24		111		96.9	Good	
ADOT	01411	10		54.34	CAP Canal Br EB	Southwest	I-10-1(30)	1982	5	2	1	92	96	22	50	50	0	1	911		97.1	Good	NHS
ADOT	01412	10		54.35	CAP Canal Br WB	Southwest	I-10-1(30)	1982	5	2	1	92	96	22	42	42	0	2	911		97.2	Good	NHS
ADOT	01414	10		59.15	CAP Canal Br WB	Southwest	I-10-1(30)	1982	5	2	1	103	107	30	42	42	0	1	911		97.1	Good	NHS
ADOT	01413	10		59.16	CAP Canal Br EB	Southwest	I-10-1(30)	1982	5	2	1	103	107	30	42	42	0	1	911		97.0	Good	NHS
ADOT	01282	10		59.47	Sore Finger Rd UP	Southwest	I-10-1(33)	1968	2	6	3	125	330	0	26	26	16.19		111		99.0	Fair	
ADOT	06205	10		65.6	RCB WB	Southwest	I-10-1(33)	1968	2	19	2	10	21	0	38	0	0				97.2	Good	NHS
ADOT	06204	10		65.61	RCB EB	Southwest	I-10-1(33)	1968	2	19	2	10	21	0	38	0	0				97.2	Good	NHS
ADOT	06281	10		67.55	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06282	10		67.55	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06283	10		67.6	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06284	10		67.6	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06207	10		67.67	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06286	10		67.67	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06208	10		67.72	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06288	10		67.72	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06289	10		67.77	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06290	10		67.77	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0				97.2	Good	NHS
ADOT	06206	10		67.82	RCB EB	Southwest	I-10-1																

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	06210	10		67.95	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06296	10		67.95	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06297	10		68.05	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06298	10		68.05	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06299	10		68.1	RCB EB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06300	10		68.1	RCB WB	Southwest	I-10-1(33)	1968	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06211	10		69.2	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0					97.2	Good	NHS
ADOT	06212	10		69.2	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0					97.2	Good	NHS
ADOT	06213	10		69.3	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	38	0	0					97.2	Good	NHS
ADOT	06214	10		69.3	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	50	0	0					82.0	Fair	NHS
ADOT	06215	10		69.4	RCB EB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	48	0	0					97.2	Good	NHS
ADOT	06216	10		69.4	RCB WB	Southwest	I-10-1(36)	1972	2	19	4	10	43	0	60	0	0					82.0	Good	NHS
ADOT	01283	10		69.66	Ave 75 E TI UP	Southwest	I-10-1(33)	1968	2	6	3	127	331	10	28	28.8	16.2		911			93.2	Fair	NHS
ADOT	06217	10		70.5	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06218	10		70.5	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.3	Good	NHS
ADOT	06219	10		70.53	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06220	10		70.53	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.3	Good	NHS
ADOT	06221	10		70.56	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06222	10		70.56	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.3	Good	NHS
ADOT	06223	10		70.59	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06224	10		70.59	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.2	Good	NHS
ADOT	06225	10		70.62	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06226	10		70.62	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.3	Good	NHS
ADOT	06227	10		70.65	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06228	10		70.65	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06229	10		70.68	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06230	10		70.68	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.3	Good	NHS
ADOT	06231	10		70.7	RCB EB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Fair	NHS
ADOT	06232	10		70.7	RCB WB	Southwest	I-10-1(36)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	01208	10		72.71	Eagle Eye Road UP	Southwest	I-10-2(7)	1967	2	6	3	126	331	10	26	26	16.33		111			95.9	Good	NHS
ADOT	06382	10		74.1	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06383	10		74.1	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06384	10		74.12	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06385	10		74.12	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06386	10		74.14	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06387	10		74.14	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06388	10		74.16	RCB EB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0		0			97.0	Good	NHS
ADOT	06389	10		74.16	RCB WB	Southwest	I-10-2(18)	1972	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06390	10		76.2	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06391	10		76.2	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06392	10		76.22	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06393	10		76.22	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06394	10		76.23	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06395	10		76.23	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06396	10		76.25	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.0	Good	NHS
ADOT	06397	10		76.25	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0					97.1	Fair	NHS
ADOT	06398	10		76.27	RCB EB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0		0			97.0	Good	NHS
ADOT	06399	10		76.27	RCB WB	Southwest	I-10-2(18)	1973	2	19	3	10	32	0	38	0	0		0			97.0	Good	NHS
ADOT	06400	10		80.84	RCB WB	Southwest	I-10-2(10)	1968	2	19	10	10	125	30	38	0	0		0			81.8	Good	NHS
ADOT	06401	10		80.85	RCB EB	Southwest	I-10-2(10)	1968	2	19	10	10	125	30	38	0	0		0			97.1	Good	NHS
ADOT	01209	10		81.21	Salome Road TI UP	Southwest	I-10-2(10)	1967	2	6	3	143	376	30	28	28	16		111			97.0	Good	NHS
ADOT	06403	10		81.69	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0		0			97.1	Good	NHS
ADOT	06402	10		81.7	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	51	0	0		0			82.0	Good	NHS
ADOT	06405	10		81.75	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0		0			97.1	Good	NHS
ADOT	06404	10		81.76	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	46	0	0		0			97.1	Good	NHS
ADOT	06407	10		81.8	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0		0			97.1	Good	NHS
ADOT	06406	10		81.81	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	44	0	0		0			97.1	Good	NHS
ADOT	06408	10		81.96	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06409	10		81.96	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06410	10		82.05	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06411	10		82.05	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0		0			97.1	Good	NHS
ADOT	06412	10		82.15	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06413	10		82.15	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06414	10		82.25	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0			-00		97.1	Good	NHS
ADOT	06415	10		82.25	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0					97.1	Good	NHS
ADOT	06416	10		82.5	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0					97.1	Good	NHS
ADOT	06417	10		82.5	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0					97.1	Good	NHS
ADOT	06418	10		82.7	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	23	30	38	0	0					97.1	Good	NHS
ADOT	06419																							

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS				
ADOT	06424	10		84.43	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0					97.1	Good	NHS			
ADOT	06425	10		84.43	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	32	0	38	0	0				-00		97.1	Good	NHS		
ADOT	06426	10		85.49	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0						97.1	Good	NHS		
ADOT	06427	10		85.5	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0						97.3	Good	NHS		
ADOT	06428	10		86.8	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0						97.1	Good	NHS		
ADOT	06429	10		86.81	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0						97.3	Good	NHS		
ADOT	06430	10		87.08	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	64	0	38	0	0						97.1	Fair	NHS		
ADOT	06431	10		87.08	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	64	0	38	0	0						97.3	Good	NHS		
ADOT	06433	10		88.09	Tenneman Wash RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0						97.3	Good	NHS		
ADOT	06432	10		88.1	Tenneman Wash RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	24	30	38	0	0						97.1	Good	NHS		
ADOT	06435	10		89.2	RCB WB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0						97.3	Fair	NHS		
ADOT	06434	10		89.21	RCB EB	Southwest	I-10-2(10)	1968	2	19	6	10	74	30	38	0	0						97.1	Good	NHS		
ADOT	06436	10		89.4	RCB EB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0						97.1	Good	NHS		
ADOT	06437	10		89.4	RCB WB	Southwest	I-10-2(10)	1968	2	19	2	10	21	0	38	0	0						97.3	Good	NHS		
ADOT	06439	10		89.55	RCB WB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0						97.3	Good	NHS		
ADOT	06438	10		89.56	RCB EB	Southwest	I-10-2(10)	1968	2	19	3	10	37	30	38	0	0						97.1	Good	NHS		
ADOT	06441	10		90.4	RCB WB	Southwest	I-10-2(10)	1968	2	19	4	10	49	30	38	0	0						97.3	Fair	NHS		
ADOT	06440	10		90.41	RCB EB	Southwest	I-10-2(10)	1968	2	19	4	10	49	30	38	0	0						97.1	Fair	NHS		
ADOT	06442	10		90.82	RCB EB	Southwest	I-10-2(13)	1970	2	19	6	10	64	0	38	0	0						97.1	Good	NHS		
ADOT	06443	10		90.82	RCB WB	Southwest	I-10-2(13)	1970	2	19	6	10	64	0	38	0	0						-00	97.3	Fair	NHS	
ADOT	06445	10		91.95	RCB WB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	38	0	0	4					97.3	Good	NHS		
ADOT	06444	10		91.97	RCB EB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	38	0	0	4					97.1	Fair	NHS		
ADOT	06446	10		93.12	RCB EB	Southwest	I-10-2(13)	1970	2	19	3	10.187	33	11	38	0	0	4					-00	97.1	Good	NHS	
ADOT	06447	10		93.12	RCB WB	Southwest	I-10-2(13)	1970	2	19	3	10.187	33	11	38	0	0	4					-00	97.3	Good	NHS	
ADOT	06448	10		93.77	RCB	Southwest	I-10-2(13)	1970	2	19	6	11.547	74	30	152	0	0	4					-00	70.0	Fair	NHS	
ADOT	01523	10		94.15	411th Ave TI UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	40	40	16.58						111	99.7	Fair		
ADOT	06449	10		94.25	RCB	Southwest	I-10-2(13)	1970	2	19	2	14.142	29	45	152	0	0	4					-00	70.0	Good	NHS	
ADOT	06450	10		94.3	RCB Ramp B	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	23	0	0	4					-00	97.8	Good	NHS	
ADOT	06451	10		94.85	RCB North Frnt Road	Southwest	I-10-2(13)	1970	2	19	3	12	37	30	26	0	0	2					-00	99.8	Fair		
ADOT	06452	10		94.9	RCB	Southwest	I-10-2(13)	1970	2	19	3	14.142	45	45	152	0	0	2					-00	70.0	Fair	NHS	
ADOT	01524	10		95.3	Old Camp Wash Br WB	Southwest	I-10-2(13)	1971	2	1	3	35	94	0	38	38	0	2					110	95.0	Fair	NHS	
ADOT	01525	10		95.3	Old Camp Wash Br EB	Southwest	I-10-2(13)	1971	2	1	3	35	94	0	38	38	0	2					110	95.0	Fair	NHS	
ADOT	01526	10		96.21	Belmont Rd UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	28	28	16.95						111	97.1	Fair		
ADOT	01527	10		96.53	Coyote Wash Br WB	Southwest	I-10-2(13)	1971	2	1	3	40	107	0	38	38	0	1					110	93.9	Good	NHS	
ADOT	01528	10		96.53	Coyote Wash Br EB	Southwest	I-10-2(13)	1971	2	1	3	40	107	0	38	38	0	2					110	93.9	Good	NHS	
ADOT	06453	10		96.75	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	4					-00	70.0	Good	NHS	
ADOT	06454	10		97.7	RCB	Southwest	I-10-2(13)	1970	2	19	3	10	32	0	152	0	0	4					-00	70.0	Fair	NHS	
ADOT	06455	10		98.2	Four Mile Wash RCB	Southwest	I-10-2(13)	1970	2	19	4	10	43	0	152	0	0	4					-00	70.0	Fair	NHS	
ADOT	06724	10		98.25	Ramp A RCB	Southwest	I-10-2(503)	1980	2	19	5	10	53	0	22	0	0	4					-00	97.7	Good	NHS	
ADOT	06726	10		98.25	Ramp C RCB	Southwest	I-10-2(503)	1980	2	19	5	10	53	0	22	0	0	4					-00	97.6	Good	NHS	
ADOT	01529	10		98.29	Wintersburg Rd TI UP	Southwest	I-10-2(13)	1971	2	6	2	120	245	15	28	28	16.4						111	89.1	Fair		
ADOT	06592	10		98.3	Wintersburg Road RCB	Southwest	I-10-2(13)	1970	2	19	2	14.142	29	45	28	0	0	4					-00	98.0	Good		
ADOT	06456	10		98.35	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	4					-00	70.0	Good	NHS	
ADOT	06725	10		98.35	RCB Ramp B	Southwest	I-10-2(503)	1980	2	19	5	8	43	0	26	0	0	4					-00	95.0	Good	NHS	
ADOT	06457	10		99.15	RCB EB	Southwest	I-10-2(13)	1970	2	19	5	10	53	0	38	0	0	4					-00	97.0	Good	NHS	
ADOT	06458	10		99.15	RCB WB	Southwest	I-10-2(13)	1970	2	19	5	10	53	0	38	0	0	4					-00	97.1	Fair	NHS	
ADOT	06459	10		100.23	RCB	Southwest	I-10-2(13)	1970	2	19	2	10	21	0	152	0	0	4					-00	71.6	Good	NHS	
ADOT	06564	10		101.35	RCB	Southwest	I-10-2(16)	1974	2	19	2	10	21	0	152	0	0	4					-00	71.6	Good	NHS	
ADOT	01647	10		101.4	355th Ave UP	Southwest	I-10-2(16)	1974	2	6	2	125	253	15	26	26	16						111	98.0	Fair		
ADOT	06565	10		101.53	RCB	Southwest	I-10-2(16)	1974	2	19	2	10	21	0	152	0	0	4					-00	71.6	Good	NHS	
ADOT	06566	10		101.66	RCB	Southwest	I-10-2(16)	1974	2	19	3	10	32	0	152	0	0	4					-00	71.6	Good	NHS	
ADOT	01644	10		103.44	339th Avenue TI UP	Southwest	I-10-2(16)	1974	2	6	2	125	253	15	28	28	16.49						111	81.1	Fair		
ADOT	06567	10		104.34	RCB	Southwest	I-10-2(16)	1974	2	19	4	10	43	0	152	0	0	4					-00	70.8	Good	NHS	
ADOT	01645	10		104.69	Hassayampa Rvr Br WB	Southwest	I-10-2(16)	1974	6	2	15	79	1180	10	38	42	0	0					911	96.9	Fair	NHS	
ADOT	01646	10		104.69	Hassayampa Rvr Br EB	Southwest	I-10-2(16)	1974	6	2	15	79	1180	10	38	42	0	0					911	96.8	Good	NHS	
ADOT	01664	10		107.6	Johnson Road UP	Southwest	I-10-2(61)	1975	2	6	2	125	253	15	26	26	16.71						111	94.3	Fair		
ADOT	02078	10		109.68	Palo Verde Rd TI UP	Southwest	I-10-2-507	1988	6	2	2	133	271	15	104	104	16.75						911	99.4	Good		
ADOT	06823	10		109.68	Palo Verde Rd RCB	Southwest	I-10-2-507	1988	2	19	4	10	43	0	94	0	0	4					-00	83.3	Good	NHS	
ADOT	04001	60		31.56	RCB	Southwest	FL-1(A)	1932	2	19	2	10	24	30	41	0	0	0						97.8	Good		
ADOT	04002	60		32.83	RCB	Southwest	FL-1(A)	1932	2	19	2	10	29	45	41	48	0	4						94.8	Good		
ADOT	04003	60		34.05	RCB	Southwest	FL-1(A)	1932	2	19	3	10	46	45	42	0	0	2						82.3	Fair		
ADOT	04004	60		34.23	RCB	Southwest	FL-1(A)	1932	2	19	3	10	46	45	41	0	0	0						-00	97.8	Fair	
ADOT	00085	60		34.44	Wash Bridge	Southwest	FL-1(A)	1932	1	1	2	22	44	0	41	43	0	4						911	80.5	Fair	
ADOT	00086	60		35.44	Wash Bridge	Southwest	FL-98(F)	1932	1	1	5	22	110	30	40	43	0	4						911	89.0	Fair	
ADOT	00087	60		3																							

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS		
ADOT	04013	60		42.1	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	0			93.5	Fair		
ADOT	04014	60		42.23	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	0			82.2	Fair		
ADOT	04015	60		42.36	RCB	Southwest	FA-98(F)	1932	2	19	5	10	53	0	42	48	0	6	000				93.5	Fair	
ADOT	04016	60		44.4	RCB	Southwest	FA-98(F)	1932	2	19	2	10	21	0	41	0	0		-00				97.7	Good	
ADOT	04017	60		45.06	RCB	Southwest	FA-98(F)	1932	2	19	2	10	21	0	40	48	0	6	000				94.8	Good	
ADOT	04018	60		46.17	RCB	Southwest	FA-98(E)	1932	2	19	3	10	32	0	41	48	0	6	000				94.5	Good	
ADOT	04019	60		46.36	RCB	Southwest	FA-98(E)	1932	2	19	3	10	32	0	41	48	0	6	000				94.5	Good	
ADOT	04020	60		46.8	RCB	Southwest	FA-98(E)	1932	2	19	4	10	43	0	41	48	0	6	000				94.5	Good	
ADOT	01406	60		46.92	US B	Southwest	USBR-DC7344	1978	5	2	1	99	101	33	44	44	0			911			98.9	Good	
ADOT	04021	60		47.52	RCB	Southwest	FA-98(E)	1932	2	19	2	10	21	0	41	48	0	6	000				94.6	Good	
ADOT	04022	60		47.94	RCB	Southwest	FA-98(E)	1932	2	19	2	10	21	0	41	48	0	6	000				94.6	Good	
ADOT	00643	72		32.13	Butler Wash Bridge	Southwest	NS-265(61)A	1961	2	1	4	30	111	0	34	34	0	2	911				80.2	Good	
ADOT	01405	72		44.1	SR 72 CAP Bridge	Southwest	DC-7298	1978	5	2	1	98	100	31	38	38	0			911			97.5	Fair	
ADOT	06695	72		44.32	CAP RCB	Southwest	DC-7298	1978	2	19	2	10	30	45	38	0	0	0					90.1	Good	
ADOT	00734	85		0.37	Gila Bend SPRR UP	Southwest	S-222(22)	1963	3	2	3	44	106	0			15.55			300			-2.0	Good	
ADOT	04553	85		0.55	RCB	Southwest	S-222(22)	1962	2	19	3	12	37	30	40	0	0	0					99.5	Fair	
ADOT	00735	85		.65	Gillespie Canal Br	Southwest	S-222(22)	1963	5	5	1	55	56	8	40	40	0	1	311				79.0	Fair	
ADOT	04554	85		2.77	RCB	Southwest	S-222(22)	1962	2	19	2	12	24	30	38	0	0	0					80.0	Good	
ADOT	04555	85		3.35	Quitotosa Wash RCB	Southwest	S-222(15)	1958	2	19	8	10	87	0	34	39.2	0	4	600				83.3	Good	
ADOT	04556	85		5.01	RCB	Southwest	S-222(15)	1958	2	19	2	12	24	30	34	39.6	0	4	600				81.7	Fair	
ADOT	04557	85		5.28	RCB	Southwest	S-222(15)	1958	2	19	7	12	88	30	34	39.2	0	4	600				83.3	Fair	
ADOT	04558	85		6.03	RCB	Southwest	S-222(19)	1959	2	19	3	10	32	0	34	39.2	0	4	600				83.3	Good	
ADOT	04559	85		6.49	RCB	Southwest	S-222(19)	1959	2	19	4	10	43	0	34	39.1	0	4	600				81.3	Good	
ADOT	04560	85		8.35	RCB	Southwest	S-222(19)	1959	2	19	2	10	21	0	34	0	0	0					86.5	Good	
ADOT	04561	85		8.94	RCB	Southwest	S-222(19)	1959	2	19	3	10	32	0	34	39.1	0	4	600				83.3	Good	
ADOT	04562	85		10.63	RCB	Southwest	S-222(21)	1960	2	19	2	10	21	0	36	0	0	0					86.5	Good	
ADOT	04563	85		10.89	RCB	Southwest	S-222(21)	1960	2	19	6	10	65	0	36	49.6	0	4	000				81.3	Good	
ADOT	04564	85		11.22	RCB	Southwest	S-222(21)	1960	2	19	2	14	30	45	36	46.5	0	6	000				83.5	Fair	
ADOT	04565	85		11.97	RCB	Southwest	S-222(21)	1960	2	19	2	10	21	0	34	0	0	0					86.5	Good	
ADOT	04566	85		12.2	RCB	Southwest	S-222(21)	1960	2	19	3	10	32	0	36	0	0	0					86.5	Good	
ADOT	04567	85		12.52	RCB	Southwest	S-222(21)	1960	2	19	4	10	43	0	34	0	0	0					86.5	Good	
ADOT	04568	85		12.83	RCB	Southwest	S-222(21)	1960	2	19	4	10	43	0	38	0	0	0					86.5	Good	
ADOT	04569	85		15.24	RCB	Southwest	S-222(21)	1960	2	19	3	10	32	0	35	42.1	0	4	000				83.5	Good	
ADOT	04570	85		17.3	RCB	Southwest	S-222(505)	1967	2	19	5	10	53	0	35	44.2	0	4	000				83.3	Good	
ADOT	04571	85		17.67	RCB	Southwest	S-222(505)	1967	2	19	2	10	21	0	35	0	0	0					86.5	Good	
ADOT	04572	85		19.05	RCB	Southwest	S-222(505)	1967	2	19	2	10	21	0	35	0	0	0					86.5	Good	
ADOT	04573	85		20.54	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	24	30	27	33.5	0	4	000				82.4	Fair	
ADOT	04574	85		23.46	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	21	0	26	28.1	0	4	000				71.7	Good	
ADOT	04575	85		23.84	RCB	Southwest	FL-10-A(1)	1939	2	19	2	10	21	0	25	28.1	0	4	000				74.0	Good	
ADOT	04576	85		23.95	RCB	Southwest	WPS-120	1937	2	19	3	10	32	0	25	28.2	0	4	000				73.8	Good	
ADOT	00176	85		27.23	Midway Wash Bridge	Southwest	FLH-10A-1	1937	2	1	4	25	101	0	28	24	0	3	400				62.8	Fair	
ADOT	04577	85		28.6	RCB	Southwest	WPS-120	1937	2	19	3	10	32	0	41	85	0	11	000				83.3	Fair	
ADOT	04442	85		120.85	RCB NB	Southwest	F-159(3)	1956	2	19	3	10	33	14	45	0	0	0					69.8	Good	NHS
ADOT	04443	85		123.84	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911				98.3	Good	NHS
ADOT	07154	85		123.86	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	10	43	0	0	0					98.3	Good	NHS
ADOT	04444	85		123.91	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911				98.3	Good	NHS
ADOT	07155	85		123.93	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	5	43	0	0	0					99.6	Good	NHS
ADOT	07156	85		124.29	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	2	11	23	25	43	0	0	0					99.6	Good	NHS
ADOT	04445	85		125.14	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	44	0	2	911				99.4	Good	NHS
ADOT	07157	85		125.16	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	65	0	43	0	0	0					99.6	Good	NHS
ADOT	04446	85		125.5	RCB NB	Southwest	F-159(3)	1956	2	19	8	10	87	0	44	44	0	2	911				98.3	Good	NHS
ADOT	07158	85		125.52	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	8	10	87	0	43	0	0	0					98.3	Good	NHS
ADOT	04447	85		125.65	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	43.8	0	2	911				99.4	Good	NHS
ADOT	07159	85		125.66	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	65	0	43	0	0	0					99.6	Good	NHS
ADOT	07160	85		125.95	RCB SB	Southwest	NH-085-B(012)B	2006	2	19	6	10	67	15	43	0	0	0					99.6	Good	NHS
ADOT	04448	85		126.22	RCB NB	Southwest	F-159(3)	1956	2	19	3	10	32	0	40	43.9	0	2	911				99.4	Good	NHS
ADOT	07121	85		126.22	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	3	10	32	0	43	0	0	0					99.6	Good	NHS
ADOT	07122	85		126.58	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0					99.6	Good	NHS
ADOT	07123	85		126.74	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	22	20	43	0	0	0					99.6	Good	NHS
ADOT	07124	85		126.8	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0					99.6	Good	NHS
ADOT	07125	85		126.84	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	12	24	30	43	0	0	0					99.6	Good	NHS
ADOT	04449	85		127.15	RCB NB	Southwest	F-159(3)	1956	2	19	6	10	65	0	40	43.9	0	2	911				98.4	Good	NHS
ADOT	07126	85		127.15	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	6	10	65	0	43	0	0	0					99.6	Good	NHS
ADOT	07127	85		127.5	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	2	10	21	0	43	0	0	0					99.6	Good	NHS
ADOT	04450	85		128.44	RCB NB	Southwest	F-159(2)	1956	2	19	3	10	32	0	40	44	0	2	911				99.6	Good	NHS
ADOT	07128	85		128.44	RCB SB	Southwest	NH-085-B(007)B	2006	2	19	3	10	32	5	43	0	0								

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	04453	85		131.99	RCB	Southwest	F-159(2)	1956	2	19	5	10	55	8	84	0	0					70.0	Good	NHS
ADOT	04454	85		132.35	RCB	Southwest	F-159(2)	1956	2	19	4	10	43	0	78	0	0					69.8	Good	NHS
ADOT	07192	85		133.01	RCB SB	Southwest	085-B(011)	2009	2	19	2	10	21	0	38	0	0					99.2	Good	NHS
ADOT	07201	85		133.01	RCB WFR	Southwest	085-B(011)	2009	2	19	2	10	21	0	32	0	0					100.0	Good	
ADOT	07202	85		133.08	RCB WFR	Southwest	085-B(011)	2009	2	19	3	10	34	18	32	0	0					100.0	Good	
ADOT	07193	85		133.1	RCB	Southwest	085-B(011)	2009	2	19	3	11	36	27	78	0	0					84.0	Good	NHS
ADOT	07203	85		133.74	RCB WFR	Southwest	085-B(011)	2009	2	19	3	10	32	0	32	0	0					100.0	Good	
ADOT	07195	85		133.78	RCB SB	Southwest	085-B(011)	2009	2	19	3	13	40	37	56	0	0					84.5	Good	NHS
ADOT	07244	85		133.84	RCB NB	Southwest	085-B(011)	2009	2	19	3	10	28	0	56	0	0					84.5	Good	NHS
ADOT	07220	85		133.86	Woods Road RCB	Southwest	085-B(011)	2009	2	19	3	10	32	0	38	0	0					100.0	Good	
ADOT	07245	85		134.62	RCB	Southwest	085-B(011)	2009	2	19	7	8	62	99	78	0	0					70.0	Good	NHS
ADOT	07198	85		134.67	RCB SB	Southwest	085-B(011)	2009	2	19	5	10	55	12	38	0	0					99.6	Good	NHS
ADOT	04455	85		134.68	RCB NB	Southwest	F-159(2)	1956	2	19	5	10	54	0	40	44	0	8	611			99.4	Good	NHS
ADOT	07199	85		135.37	RCB SB	Southwest	085-B(011)	2009	2	19	3	10	32	3	38	0	0					99.6	Good	NHS
ADOT	04456	85		135.38	RCB NB	Southwest	F-159(1)	1956	2	19	3	10	32	0	44	0	0	2				99.6	Fair	NHS
ADOT	04457	85		136.95	RCB EFR	Southwest	F-159(1)	1956	2	19	3	10	32	0	44	44.1	0	8	611			99.8	Good	NHS
ADOT	07200	85		136.99	RCB	Southwest	085-B(011)	2009	2	19	3	10	32	0	76	0	0					84.0	Good	NHS
ADOT	02524	85		138.38	Lewis Prison RD T1 OP NB	Southwest	085-B(005)	2005	5	2	1	132	138	0	38	42	16.86		911			100.0	Good	NHS
ADOT	02680	85		138.38	Lewis Prison RD T1 OP SB	Southwest	085-B(005)	2005	5	2	1	132	138	0	38	42	16.73		911			100.0	Good	NHS
ADOT	07074	85		138.56	RCB	Southwest	F023-1-526	1999	2	19	5	12	64	33	32	0	0					99.9	Fair	
ADOT	07111	85		138.64	RCB EFR	Southwest	NH-085-B(005)B	2006	2	19	3	10	32	7	54	0	0					100.0	Good	
ADOT	07110	85		138.66	RCB	Southwest	NH-085-B(005)B	2006	2	19	3	10	32	10	90	0	0					83.4	Good	NHS
ADOT	07136	85		138.66	RCB WFR	Southwest	085-B(009)B	2008	2	19	3	10	32	20	38	0	0					99.9	Good	
ADOT	07137	85		139.9	RCB	Southwest	085-B(009)B	2008	2	19	5	10	55	10	81	0	0					70.0	Good	NHS
ADOT	00466	85		141.08	Rainbow Wash Bridge NB	Southwest	F-159(1)	1956	2	1	3	30	81	0	42	41.8	0	2	911			92.2	Good	NHS
ADOT	02771	85		141.1	Rainbow Wash Bridge SB	Southwest	085-B(009)B	2008	2	1	6	34	202	3	38	42	0	0	911			99.4	Good	NHS
ADOT	04458	85		141.61	RCB	Southwest	F-159(1)	1956	2	19	5	10	54	7	85	0	0					69.8	Good	NHS
ADOT	02279	85		147.75	Gila River Bridge SB	Southwest	AC-STP-023-1(19)	1995	6	2	28	129	3625	0	38	42	0	0	911			99.5	Fair	NHS
ADOT	02280	85		147.75	Gila River Bridge NB	Southwest	AC-STP-023-1(24)B	2000	6	2	28	129	3625	0	38	42	0	0	911			99.5	Good	NHS
ADOT	07172	85		150.51	BW/CDD Canal RCB	Southwest	STP-085-B(13)A	2007	2	19	2	10	21	13	98	0	0	0	00			80.4	Good	NHS
ADOT	01790	85		153.35	Roosevelt Canal Br NB FR	Southwest	F-023-1-505	1976	5	5	1	40	43	24	28	41.3	0	2	911			100.0	Good	
ADOT	01504	95		22.39	E Main Canal Br	Southwest	SU-264(10)	1969	5	2	1	72	76	0	64	64	0		211			93.4	Fair	NHS
ADOT	00504	95		33.55	Gila Canal Br	Southwest	NS-264(57)A	1957	1	4	3	36	110	9	40	40	0	2	500			82.5	Fair	
ADOT	20035	95		34.46	Fortuna Wash Bridge	Southwest	NH-TCSF-005-B(201)T	2016	2	1	15	43.5	602	15	84	84	0	0	911			84.9	Good	NHS
ADOT	00343	95		38	Weilton Mohawk Canal Bridge	Southwest	FA5-264(S0)B	1950	2	4	3	31	94	20	28	28	0	3	500			61.0	Fair	
ADOT	02408	95		38.83	Gila River Br	Southwest	ER-063-1(9)	1993	5	5	16	43	685	45	48	46.3	0	2	411			98.3	Fair	
ADOT	05006	95		42.5	RCB	Southwest	S-264(3)	1957	2	19	3	10	32	0	60	0	0	3	600			81.2	Fair	NHS
ADOT	05007	95		46.8	RCB	Southwest	S-264(3)	1957	2	19	4	10	43	0	34	0	0					80.0	Fair	NHS
ADOT	00583	95		53.28	Castle Dome Wash Br	Southwest	NS-264(61)A	1961	2	1	6	30	171	45	34	32.3	0	1	911			73.6	Fair	NHS
ADOT	07109	95		55.92	RCB	Southwest	U-095-B-504	2003	2	19	4	10	49	30	40	0	0	000				82.8	Good	NHS
ADOT	05008	95		73.98	RCB	Southwest	NFS-264(61)B	1963	2	19	3	10	32	0	40	0	0					65.0	Good	NHS
ADOT	05009	95		75.7	RCB	Southwest	S-264(8)	1967	2	19	3	8	26	0	36	0	0					80.9	Fair	NHS
ADOT	05010	95		76.74	RCB	Southwest	S-264(8)	1967	2	19	4	10	43	0	36	0	0					80.1	Fair	NHS
ADOT	05011	95		77.27	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	36	0	0					69.0	Fair	NHS
ADOT	05012	95		77.47	RCB	Southwest	S-264(8)	1967	2	19	2	10	21	0	35	0	0					80.9	Fair	NHS
ADOT	05013	95		77.97	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0					80.9	Fair	NHS
ADOT	05014	95		79.01	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0					69.0	Fair	NHS
ADOT	05015	95		79.75	RCB	Southwest	S-264(8)	1967	2	19	5	10	54	0	35	0	0					69.0	Fair	NHS
ADOT	05016	95		80.41	RCB	Southwest	S-264(8)	1967	2	19	3	10	32	0	35	0	0					80.9	Fair	NHS
ADOT	05017	95		81.23	RCB	Southwest	S-264(9)	1968	2	19	2	10	21	0	35	0	0					80.9	Good	NHS
ADOT	05018	95		81.57	RCB	Southwest	S-264(9)	1968	2	19	4	10	43	0	35	0	0					80.9	Good	NHS
ADOT	05019	95		82.27	RCB	Southwest	S-264(9)	1968	2	19	6	10	64	0	35	0	0					80.9	Good	NHS
ADOT	05020	95		82.67	RCB	Southwest	S-264(9)	1968	2	19	6	10	64	0	35	0	0					80.9	Good	NHS
ADOT	05021	95		83.63	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0					80.9	Good	NHS
ADOT	05022	95		84.35	RCB	Southwest	S-264(9)	1968	2	19	2	10	21	0	35	0	0					80.9	Good	NHS
ADOT	05023	95		84.86	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0					80.9	Good	NHS
ADOT	05024	95		85.24	RCB	Southwest	S-264(9)	1961	2	19	3	8	26	0	35	0	0					80.9	Good	NHS
ADOT	05025	95		85.58	RCB	Southwest	S-264(9)	1968	2	19	5	10	53	0	35	0	0					80.9	Good	NHS
ADOT	05026	95		86.44	RCB	Southwest	S-264(9)	1968	2	19	3	8	26	0	38	0	0					80.9	Good	NHS
ADOT	05027	95		93.9	RCB	Southwest	NS-264(S02)	1962	2	19	4	10	49	30	28	0	0					80.9	Good	NHS
ADOT	07117	95		96.02	RCB	Southwest	U-095-B-503	2005	2	19	3	10	32	10	44	0	0					80.9	Good	NHS
ADOT	05028	95		97.95	RCB	Southwest	NS-264(S02)	1962	2	19	4	10	43	0	28	0	0	7	-00			77.9	Good	NHS
ADOT	05029	95		99.88	RCB	Southwest	NS-264(61)B	1961	2	19	6	10	64	0	28	0	0					80.0	Good	NHS
ADOT	05031	95		103.8	RCB	Southwest	S-264(S12)	1969	2	19	6	10	75	30	34	0	0					99.2	Good	NHS
ADOT	05030	95		104.1	RCB	Southwest	I-10-1(5)	1964	2	19	3	12	37	30	62	0	0					83.5	Good	NHS
ADOT	02046	95		109.67	Plomosa Wash Bridge	Southwest	F-063-2-912	1987	2	1	3	30	83	15	68	68	0		411			80.0	Fair	NHS
ADOT	07084	95		110.14	Scaddan Wash RCB	Southwest	NH-063-2(25)	2001	2	19	6	10	90	45	68	0	0	3	300			80.6	Good	NHS
ADOT	07083	95		110.5	Plymouth Wash RCB	Southwest	063-2(25)B	2001	2</															

ARIZONA STATE HIGHWAY SYSTEM BRIDGE RECORD

As of 4/12/2021

Sorted by Route and Milepost

Agency	Str No	Rt No	Rt Suffix	Rt MP	Bridge Name	District	Original Construction Project No	Year Built	Mat	Type	No of Spans	Max Span Length Ft	Structure Length Ft	Skew	Roadway Appr Width Ft	Bridge Roadway Width Ft	Allow Vert Clearance Ft	Overlay In	Bridge Rail Type	Def	SR	Bridge Condition	NHS	
ADOT	06819	95		148.33	Osborne Wash RCB	Southwest	B-063-2-506	1986	2	19	4	6	30		72	0	0					65.0	Good	NHS
ADOT	02029	95		148.5	Rio Vista Rd UP	Southwest	B-063-2-506	1986	5	6	1	168	171	14	34	38	28.74			911		98.0	Fair	
ADOT	02403	95		154.9	Buckskin Ped UP	Southwest	N-900-559	1994	5	2	1	135	140	0			18.33			600		-2.0	Good	
ADOT	06015	95		156.43	RCB	Southwest	N5-405(61)A	1961	2	19	2	10	29	45	36	0	0					84.9	Good	NHS
ADOT	07239	95		156.71	Giers Wash RCB	Southwest	095-C(202)	2011	2	19	2	10	21	0	34	0	0					98.7	Good	NHS
ADOT	06016	95		156.82	Giers Wash RCB	Southwest	N5-405(61)A	1961	2	19	3	10	32	0	35	0	0					84.9	Fair	NHS
ADOT	01407	95		160.86	CAP Canal Intake Br	Southwest	USBR-344	1981	4	7	3	133	335	0	38	38	0			911		79.0	Good	NHS
ADOT	01272	95		161.62	Bill Williams Riv Br	Southwest	S-405(4)	1967	5	2	14	76	1126	0	33	32.4	0	1		911		82.8	Fair	NHS
ADOT	02708	195		18.17	County 19th Street OP NB	Southwest	STP-900-A(055)	2009	1	1	1	47	49	0	40	42	19.18			911		99.4	Good	NHS
ADOT	02709	195		18.17	County 19th Street OP SB	Southwest	STP-900-A(055)	2009	1	1	1	47	49	0	40	42	19.02			911		99.4	Good	NHS
ADOT	02963	195		27.13	B Lateral Canal Br	Southwest	S-263(4)	1971	5	5	1	36	38	1	91	112	0			311		85.0	Fair	
ADOT	02964	195		27.38	UPRR UP	Southwest	SG263(3)	1969	5	5	4	42	139	9			15.47			100		-2.0	Good	
CAWCD	00984	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	76	154	0	28	40	0			911		99.9	Good	
CAWCD	00985	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	82	165	0	28	40	0			911		99.8	Good	
CAWCD	00986	0	0	0	CAP Canal Bridge	Southwest	DC-7298	1980	5	2	1	85	87	0	28	28	0			911		98.0	Good	
CAWCD	00987	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1985	5	2	1	91	93	23	28	32	0	1		911		99.9	Good	
CAWCD	00988	0	0	0	CAP Canal Bridge	Southwest	3D-C7477	1985	5	2	1	101	103	32	32	32	0			911		99.8	Good	
CAWCD	00989	0	0	0	CAP Canal Bridge	Southwest	3D-C7477	1985	5	2	1	87	89	16	24	24	0			911		94.5	Good	
CAWCD	00990	0	0	0	CAP Canal Bridge	Southwest	DC-7195	1977	5	2	1	85	87	9	42	32	0			911		94.9	Fair	
CAWCD	00992	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	2	83	168	0	28	40	0			911		99.9	Good	
CAWCD	00993	0	0	0	CAP Canal Bridge	Southwest		1982	5	2	1	83	85	0	20	20	0			911		92.8	Fair	
CAWCD	00994	0	0	0	CAP Canal Bridge	Southwest		1981	5	2	1	83	85	0	20	20	0			911		92.8	Good	
CAWCD	00995	0	0	0	CAP Canal Bridge	Southwest		1982	5	2	1	88	90	18	20	20	0			911		97.9	Good	
CAWCD	00996	0	0	0	CAP Canal Bridge	Southwest		1981	5	2	1	86	88	0	36	36	0			911		98.0	Good	
CAWCD	01487	0	0	0	CAP Canal Bridge	Southwest	DC-7394	1981	5	2	1	84	85	0	34	32	0	3		911		88.9	Good	
CAWCD	01844	0	0	0	CAP Canal Bridge	Southwest	3D-C7489	1983	5	2	1	101	103	26	28	40	0			911		99.9	Good	